

M/s. Sanjay Rane and Associates
Licensed Site Supervisor

183/10, Milap CHSL, Sector 1, Charkop, Kandivali (West), Mumbai – 400067

FORM-2A

[See MahaRERA order no. of 2018]

ENGINEER'S CERTIFICATE FOR QUALITY ASSURANCE

Quality Assurance Certificate

(Certificate no. 1 for the quarter ending November 2019 to February 2020)

To,
M/s. Bombay Real Estate Development Co. Pvt Ltd.,
Noshirwan Mension, Henry Road,
Colaba, Mumbai – 400 001

Subject:- Certificate for quality of materials used and quality of Construction and workmanship for the Work of Proposed residential building for Wing A, wing B and Wing C of the Phase 1, Phase 2 and Phase 3 of the project situated on the plot bearing C.T.S. No. 809A/1/1/6 & 809A/1/1/7 Of village Poisar, at Thakur Village road at Kandivali (East), Mumbai - 400101 demarcated by its boundaries (latitude and longitude of the end points) 27.45 m wide MCGM Road to the North, CTS No. 809A/1/1/8 to 10 to the South, 36.60m Wide MCGM Road to the East, 13.40m wide MCGM Road to the West of Division R/S village Poisar taluka Borivali District Mumbai suburban having Pin Code 400 101 admeasuring 6,362.40 sq.mtrs. area being developed by M/s. Bombay Real Estate Development Co. Pvt Ltd.

Reference: MahaRERA Registration Number:-

P51800023099 (SAVANA Phase 1)

P51800023159 (SAVANA Phase 2)

P51800023183 (SAVANA Phase 3)

Sir,

I/ We Shri. Sanjay Sugandha Suresh Rane of M/s. Sanjay Rane & Associates have undertaken an assignment of supervision of this real estate project.

Our Responsibility: -

To carry out the work in accordance with the development permission and as per the approved plan and submit certificate of supervision of work and to carry out material testing in-situ or in the authorized laboratory and to ensure quality of work and workmanship as per prescribed specifications, and as per NBC and or other relevant code of practise.

1. Material Testing :-

I/we, have applied following mandatory checks on the basic materials, used in the construction.

M/s. Sanjay Rane and Associates

Licensed Site Supervisor

183/10, Milap CHSL, Sector 1, Charkop, Kandivali (West), Mumbai – 400067

i. Cement-

It has been tested for its fineness, soundness, setting time, compressive strength etc. as per IS code 3535:1986 or as per other relevant IS/85/NBC code, or as per industry standards and its results are within the permissible limits.

ii. Coarse aggregate –

It has been tested, for deleterious materials, clay lumps, crushing value, impact value as per IS 24301:1986 or as per other relevant IS/BS/NBC code or as per industry standards and its results are within the permissible limits.

iii. Bricks/ blocks –

They have been tested for water absorption, crushing strength etc. as per IS 5454:1978 or as per other relevant IS/85/NBC code or as per industry standards and its results are within permissible limits.

iv. Concrete/Ready-mix Concrete-

It has been tested for compressive strength for various periods as per IS 456:2000 and IS 1199 or as per other relevant IS/BS/NBC codes, as per industry standards and its results are within permissible limits.

v. Steel for concrete-

It has been tested as per IS 2062:2011 or as per other relevant IS/BS/NBC code or as per industry standards for tensile strength, elongation and gauge length etc. and its results are within permissible limits.

vi. Testing of Other materials

Other materials like sand, crushed sand, floor tiles, fixtures and fittings, pipes and sanitary fittings etc. (List out all items) used in this project conform to relevant IS/BS/NBC code or as per standards laid down by the industry for a particular material.

2. Workmanship: -

I/ we hereby certify that work has been carried out under our supervision. We further certify that workmanship and quality is satisfactory and up to the mark and the work has been acceptable within the permissible limits of deviations as per relevant code of practice.

3. Electrical Materials and workmanship: –

Works of all the electrical wiring/connections/lift installation/other electrical installations have been carried out under authorized/registered electrical engineer and its records has been maintained. The materials used conform to the relevant I.S/ B.S/ National Building codes or as per industry standards.

M/s. Sanjay Rane and Associates

Licensed Site Supervisor

183/10, Milap CHSL, Sector 1, Charkop, Kandivali (West), Mumbai – 400067

4. Structural engineer: –

Promoters has engaged structural engineer Mr. Ashwin M. Gade of KPM ENGINEERING having Licenses no.STR/G/118 having office no. A/102, Sai Darshan Apartment, Belvali, Badalapur (West). The structural design of buildings in this project has been done under his supervision. He has checked the soil report before laying PCC for foundation in consultation with soil consultant. The formwork and concrete mix design have been done as per IS-10262:2009 or as per other relevant codes as applicable. His periodic checks and certificates for STABILITY and SAFETY have been kept on record.

5. Preservation of records: –

Record of all test results of this project have been properly kept in the prescribed formats and will be preserved at least up to the defect liability period or for the period as required by any other provision of law.

Note:- This Certificate is issued as per the CC is granted upto Plinth level only as per Zero FSI IOD plan dt.05.11.2019 by the MCGM authority.

Yours Faithfully
Sanjay Suresh

Rane

Shri. Sanjay Sugandha Suresh Rane

R/184/SS-II

Licensed Site Supervisor

M/s. Sanjay Rane & Associates

+919819987826

Digitally signed by Sanjay Suresh Rane
DN: c=IN, o=Personal, postalCode=400067, st=Maharashtra,
2.5.4.20=664297775ba331b71d5baf223021c8a4b7cdd309c5
5491a7e0c18a0a79,
serialNumber=2d865313a1c14450ba7ae180842d485,
2.5.4.45=012100029A9F00AE33436D0A0083747B0100BEC57EC773
40P500B85A7EBD92018368,
serialNumber=5a1da0915a0e0a2d21692d4c19bc52e3a65a5e1c5d
946dcd4f4d0136675ea, cn=Sanjay Suresh Rane
Date: 2020.03.11 09:26:38 +05'30'