



Dharmniti Construction Pvt. Ltd

📍 1 Anand Nagar Deopur Dhule, Maharashtra, India, 424002

☎ 02562 240859 ✉ dharmniti.construction@gmail.com

ANNEXURE A

FORM – 2A

[See Regulation 3A.]

ENGINEER'S CERTIFICATE FOR QUALITY ASSURANCE

(Site Supervisor's Certificate)

(To be submitted at end of the Financial Year)

Date: 31/03/2026

To,

DHARMANITI CONSTRUCTION PVT. LTD.

1, ANAND NAGAR, DEOPUR, DHULE.

QUALITY ASSURANCE CERTIFICATE

(Certificate No .1 for the year ending 2025-26)

Subject: Certificate for quality material used and quality of construction and workmanship for the work of **NAKSHATRA AVENUE** having MahaRERA Registration Number **P49800048215** being developed by **DHARMANITI CONSTRUCTION PVT. LTD.**


Sir,

I/We **BHAVSAR & ASSOCIATES** have undertaken the assignment of supervision of this real estate project.

Our Responsibility.

To carry out the work in accordance with the development permission and as per the approved plan, to submit certificate of supervision of work, to carry out material testing in-situ or in an authorized laboratory as per prevailing and applicable standards, to ensure quality of work and workmanship as per prescribed specifications, and as per NBC and/or other relevant code of practice.

The details of the quality are as follows:





Dharmniti Construction Pvt. Ltd

📍 1 Anand Nagar Deopur Dhule, Maharashtra, India, 424002

☎ 02562 240859 ✉ dharmniti.construction@gmail.com

1. Structural Design, Stability and Testing

Sr No.	Parameters	Yes	No	Remarks
1.	Whether soil investigations of the site have been conducted before the structural design and soil parameters have been accounted for in the structural design/drawings?	YES		OK
2.	Whether Structural Engineer has been appointed for the project?	YES		OK
3.	Whether the inspection registers, site order book and quality control test registers are maintained at the site properly and endorsed by the Engineer-in-Charge?	YES		OK
4.	Whether testing facilities to check quality of material is available at site?	YES		OK
5.	Whether the statutory provision for disaster resistance/earthquake resistant design have been incorporated, specially in case of multistoried construction?	YES		OK
6.	Has suitable cognizance been taken on demarcated flood lines and appropriate precautions taken for protecting the site from flooding considering local flooding issues?			NOT APPLICABLE



Dharmniti Construction Pvt. Ltd

📍 1 Anand Nagar Deopur Dhule, Maharashtra, India, 424002

☎ 02562 240859 ✉ dharmniti.construction@gmail.com

2. Input Materials

Sr No.	Parameters	Yes	No	Remarks
1.	Whether the following building materials confirm to relevant IS/BS/NBC Code, or per Industry Standards? If yes, provide details:			
	A. Cement, Concrete and Coarse Aggregate	YES		OK
	B. Steel and its alloy	YES		OK
	C. Electrical wire, fittings and accessories	YES		OK
	D. Plumbing and sanitary fittings	YES		OK
2.	Whether regular tests of materials and construction products are being done from accredited labs also? If yes, details of such labs		NO	
3.	Whether manufacturer test certificate for cement, steel, pipes etc. have been obtained and whether supply records are being maintained?		NO	
4.	Whether suitable water is being used for construction?	YES		OK
	A. What is the source of water?			BORING
	B. Has water been tested and approved by Engineer-in-Charge before construction?		NO	
	C. Has water been tested subsequently as per requirement?		NO	



Dharmniti Construction Pvt. Ltd

📍 1 Anand Nagar Deopur Dhule, Maharashtra, India, 424002

☎ 02562 240859 ✉ dharmniti.construction@gmail.com

3. Quality of Workmanship

Sr No.	Parameters	Yes	No	Remarks
1.	Whether works of all the electrical wiring/ connections/ lift installation / other electrical installations have been carried out under authorized /registered electrical engineer and whether records of the same has been maintained?		NO	
2.	Whether all related works of plumbing & sanitary including installation of water supply systems, drainage systems, sewage systems, sinks, toilets etc. have been carried out under authorized /registered plumbers / sanitary contractors and whether records of the same has been maintained?		NO	
3.	Whether all the work is being carried out under supervision of experienced and skilled professional? Further, whether the workmanship and quality is satisfactory and up to the mark and the work is within the acceptable and permissible limits of deviations as per relevant Code of Practice?	YES		OK
4.	Whether remedial measures are undertaken to prevent dampness	YES		China Mosaic, Toilet Waterproofing



Dharmniti Construction Pvt. Ltd

📍 1 Anand Nagar Deopur Dhule, Maharashtra, India, 424002

☎ 02562 240859 ✉ dharmniti.construction@gmail.com

	and leakages? If yes, provide details			
5.	Whether safety precautions are undertaken during construction activities for all type of workers?	YES		OK

4. Miscellaneous

Sr No.	Parameters	Yes	No	Remarks
1.	Whether third party quality inspection is being carried out on site during/after completion of the works? If yes, provide details.		no	
2.	Whether anti-termite treatment has been undertaken for the soil?	YES		OK
3.	Whether fire-fighting arrangements has been undertaken under supervision of fire consultant?		NO	
4.	Whether proper signages have been installed on site/ completed building as per requirement?	YES		OK
5.	Whether precautions are undertaken to avoid air pollution during construction? Please specify.	YES		Use of green nets
6.	Whether records of all test reports / results have been properly kept in the prescribed formats and whether the same are available at site for viewing by allottees and to	YES		OK



Dharmniti Construction Pvt. Ltd

1 Anand Nagar Deopur Dhule, Maharashtra, India, 424002

02562 240859 dharmniti.construction@gmail.com

	be handed over to the association of allottees?			
7.	Whether all relevant records including sanctioned building plans, utility drawings, various test reports / results have been properly kept in the prescribed formats to be handed over to the association of allottees?	YES		OK
8.	Any innovative/ cost effective/ green technology has been used for improving quality/energy efficiency? Please specify		NO	

Yours Faithfully,

H.J. Bhav

BHAVSAR & ASSOCIATES
Architect's & Engineer
Opp. Deopur Police Station
Road, Dhule 424002

Signature of Engineer

Date: 31/03/2026

Agreed and Accepted By:

Sehul

Signature of Promoter

Date: 31/03/2026

