

Ar. Vrushali Bobade

Architectural Planning &
Designing

Reg. No:- CA/2017/85319

H-11 ,Mhada Colony, Opp, Kidzee School,Ram Nagar Akola – 444
005 Mobile : 86004 87550 E- mail:
vrushalibobade25@gmail.com

Annexure A

FORM 1

[see Regulation 3]

ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from
Designated Account)

Date: 17/07/26.

To,
SPH ASSOCIATES
AKOLA, MAHARASHTRA, 444001

Subject : Certificate of percentage of Work of completion of construction work of **The Tulip Tower** having
MahaRERA Registration Number **P50100056480** (Only Applicable after project Registration) being developed by
SPH ASSOCIATES

Sir,

I/We **VAISHALI BOBADE** have undertaken assignment as Architect /Licensed Surveyor of certifying Percentage of
completion of Construction Work of **The Tulip Tower** having MahaRERA Registration Number **P50100056480** (Only
Applicable after project Registration, being developed by **SPH ASSOCIATES**)

Based on Site Inspection,with respect to Layout / each of the Building/Wing of the aforesaid Real Estate Project I
certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real
Estate Project under MahaRERA is as per Table A herein below. The percentage of the work executed with respect to
each of the activity of the entire phase is detailed in Table B.

Table A

Layout/Building/Wing Number: The Tulip Tower/NA


Sr. No.	Tasks/Activity	Percentage of Actual Work Done (As on date of the Certificate)
(1)	(2)	(3)
1	Excavation	100.00
2	Basements (if any)	100.00
3	Podiums (if any)	0.00
4	Plinth,	100.00
5	Stilt Floor	0.00
6	Slabs of Super Structure	100.00
7	Internal walls, Internal plaster, Floorings, Floors and windows within Flats/Premises	50.00
8	Sanitary Fitting within the Flat/Premises	25.00

Sr. No.	Tasks/Activity	Percentage of Actual Work Done (As on date of the Certificate)
9	Staircases, lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	25.00
10	External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/wing.	10.00
11	Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection,paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Any other activities.	5.00

Table B - Common Areas (Internal and External Development Works) in respect of Registered Phase / Project Number)

Sr.No	Common areas and facilities	Is Available (Yes / No)	Percentage of Actual Work Done (As on date of the Certificate)	Details
(1)	(2)	(3)	(4)	(5)
1	Internal Roads & Footpaths	No	0.00	NA
2	Water Supply	Yes	10.00	Borewell
3	Sewerage (Chamber, Lines, Septic Tank , STP)	Yes	30.00	Septic tank
4	Storm Water Drains	No	0.00	NA
5	Landscaping & Tree Planting	No	0.00	NA
6	Street Lighting	No	0.00	NA
7	Community Buildings	No	0.00	NA
8	Treatment And Disposal Of Sewage And Sullage Water	No	0.00	NA
9	Solid Waste Management And Disposal	No	0.00	NA
10	Water conservation /Rain water harvesting	Yes	0.00	Rain water Harvesting
11	Energy managemcnt	No	0.00	NA
12	Fire protection and fire safety requirements	Yes	20.00	Fire Extingusher
13	Electrical meter room, sub-station, receiving station	Yes	0.00	Electrical Meter Room
14	Aggregate area of recreational Open Space	No	0.00	NA
15	Open Parking	No	0.00	NA

Yours Faithfully



VAISHALI BOBADE

Signature & Name (IN BLOCK LETTERS) of L.S/ Architect

(License No: CA/2017/85318)

Ar. Vrushali V. Bobade

Date of Certificate: *17/07/2025*

Agreed and accepted by: *Si. Khan*

Signature of Promoter

Name: SPH Associates

Date: *17/07/2025*