

FORM 1

(See Regulation 3)

ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)

Date: 11.01.2025

To,
Parakh Realities,
379, Jaikisanwadi, Jalgaon

Subject: Certificate of Percentage of Completion of Construction Work of PPRL BASERA - JAYNAGAR having MahaRERA Registration Number - P49900050211 being developed by Parakh Realities

Sir,

We UB Architects have undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of PPRL BASERA - JAYNAGAR having MahaRERA Registration Number - P49900050211 being developed by Parakh Realities

Based on Site Inspection, with respect to Wing of the aforesaid Real Estate Project. I certify that as on the date of this certificate, the Percentage of Work done for each of the Real Estate Project under MahaRERA is as per Table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

Table A

Cluster No. 1

Sr. No (1)	Tasks /Activity (2)	Percentage of Actual work done (as on the date of certificate) (3)
1	Excavation	100
2	Plinth	75
3	Slabs of Super Structure	0
4	Internal walls, Internal Plaster, Floorings, Doors and Windows within Flats/Premises	0
5	Sanitary Fittings within the Flat/Premises	0
6	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	0
7	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0
	Overall	25%

Sr. No (1)	Tasks /Activity (2)	Percentage of Actual work done (as on the date of certificate) (3)
1	Excavation	100
2	Plinth	75
3	Slabs of Super Structure	0
4	Internal walls, Internal Plaster, Floorings, Doors and Windows within Flats/Premises	0
5	Sanitary Fittings within the Flat/Premises	0
6	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	0
7	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0
	Overall	25%

Cluster No. 4

Sr. No (1)	Tasks /Activity (2)	Percentage of Actual work done (as on the date of certificate) (3)
1	Excavation	100
2	Plinth	40
3	Slabs of Super Structure	0
4	Internal walls, Internal Plaster, Floorings, Doors and Windows within Flats/Premises	0
5	Sanitary Fittings within the Flat/Premises	0
6	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	0
7	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0
	Overall	20%

Cluster No. 5

Sr. No (1)	Tasks /Activity (2)	Percentage of Actual work done (as on the date of certificate) (3)
1	Excavation	100
2	Plinth	40

3	Slabs of Super Structure	0
4	Internal walls, Internal Plaster, Floorings, Doors and Windows within Flats/Premises	0
5	Sanitary Fittings within the Flat/Premises	0
6	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	0
7	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0
Overall		20%

Cluster No. 6

Sr. No (1)	Tasks /Activity (2)	Percentage of Actual work done (as on the date of certificate) (3)
1	Excavation	100
2	Plinth	100
3	Slabs of Super Structure	100
4	Internal walls, Internal Plaster, Floorings, Doors and Windows within Flats/Premises	100
5	Sanitary Fittings within the Flat/Premises	100
6	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	100
7	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	100
Overall		100%

Cluster No. 7

Sr. No (1)	Tasks /Activity (2)	Percentage of Actual work done (as on the date of certificate) (3)
1	Excavation	100
2	Plinth	100
3	Slabs of Super Structure	100
4	Internal walls, Internal Plaster, Floorings, Doors and Windows within Flats/Premises	100
5	Sanitary Fittings within the Flat/Premises	100
6	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	100

7	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	100
	Overall	100%

Cluster No. 8

Sr. No (1)	Tasks /Activity (2)	Percentage of Actual work done (as on the date of certificate) (3)
1	Excavation	100
2	Plinth	100
3	Slabs of Super Structure	100
4	Internal walls, Internal Plaster, Floorings, Doors and Windows within Flats/Premises	100
5	Sanitary Fittings within the Flat/Premises	100
6	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	100
7	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	100
	Overall	100%

Cluster No. 9

Sr. No (1)	Tasks /Activity (2)	Percentage of Actual work done (as on the date of certificate) (3)
1	Excavation	100
2	Plinth	100
3	Slabs of Super Structure	100
4	Internal walls, Internal Plaster, Floorings, Doors and Windows within Flats/Premises	100
5	Sanitary Fittings within the Flat/Premises	100
6	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	100

7	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	100
	Overall	100%

Cluster No. 10

Sr. No (1)	Tasks /Activity (2)	Percentage of Actual work done (as on the date of certificate) (3)
1	Excavation	100
2	Plinth	100
3	Slabs of Super Structure	100
4	Internal walls, Internal Plaster, Floorings, Doors and Windows within Flats/Premises	100
5	Sanitary Fittings within the Flat/Premises	100
6	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	100
7	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	100
	Overall	100%

Cluster No. 11

Sr. No (1)	Tasks /Activity (2)	Percentage of Actual work done (as on the date of certificate) (3)
1	Excavation	100
2	Plinth	100
3	Slabs of Super Structure	100
4	Internal walls, Internal Plaster, Floorings, Doors and Windows within Flats/Premises	100
5	Sanitary Fittings within the Flat/Premises	100

6	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	100
7	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	100
	Overall	100%

Cluster No. 12

Sr. No (1)	Tasks /Activity (2)	Percentage of Actual work done (as on the date of certificate) (3)
1	Excavation	100
2	Plinth	100
3	Slabs of Super Structure	32
4	Internal walls, Internal Plaster, Floorings, Doors and Windows within Flats/Premises	0
5	Sanitary Fittings within the Flat/Premises	0
6	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	0
7	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0
	Overall	33%

Cluster No. 13

Sr. No (1)	Tasks /Activity (2)	Percentage of Actual work done (as on the date of certificate) (3)
1	Excavation	100
2	Plinth	100
3	Slabs of Super Structure	32
4	Internal walls, Internal Plaster, Floorings, Doors and Windows within Flats/Premises	0
5	Sanitary Fittings within the Flat/Premises	0
6	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	0
7	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0
	Overall	33%

Sr. No (1)	Tasks /Activity (2)	Percentage of Actual work done (as on the date of certificate) (3)
1	Excavation	100
2	Plinth	100
3	Slabs of Super Structure	32
4	Internal walls, Internal Plaster, Floorings, Doors and Windows within Flats/Premises	0
5	Sanitary Fittings within the Flat/Premises	0
6	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	0
7	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0
	Overall	33%

Cluster No. 16

Sr. No (1)	Tasks /Activity (2)	Percentage of Actual work done (as on the date of certificate) (3)
1	Excavation	100
2	Plinth	100
3	Slabs of Super Structure	100
4	Internal walls, Internal Plaster, Floorings, Doors and Windows within Flats/Premises	100
5	Sanitary Fittings within the Flat/Premises	64
6	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	0
7	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0
	Overall	66%

Cluster No. 17

Sr. No (1)	Tasks /Activity (2)	Percentage of Actual work done (as on the date of certificate) (3)
1	Excavation	100
2	Plinth	100
3	Slabs of Super Structure	70

4	Internal walls, Internal Plaster, Floorings, Doors and Windows within Flats/Premises	0
5	Sanitary Fittings within the Flat/Premises	0
6	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	0
7	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0
Overall		38%

Shopping 1

Sr. No (1)	Tasks /Activity (2)	Percentage of Actual work done (as on the date of certificate) (3)
1	Excavation	100
2	Plinth	100
3	Slabs of Super Structure	25
4	Internal walls, Internal Plaster, Floorings, Doors and Windows within Flats/Premises	0
5	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0
Overall		45%

Shopping 2

Sr. No (1)	Tasks /Activity (2)	Percentage of Actual work done (as on the date of certificate) (3)
1	Excavation	100
2	Plinth	100
3	Slabs of Super Structure	25
4	Internal walls, Internal Plaster, Floorings, Doors and Windows within Flats/Premises	0
5	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0
Overall		45%

Shopping 3

Sr. No (1)	Tasks /Activity (2)	Percentage of Actual work done (as on the date of
---------------	------------------------	--

		certificate)
		(3)
1	Excavation	100
2	Plinth	100
3	Slabs of Super Structure	50
4	Internal walls, Internal Plaster, Floorings, Doors and Windows within Flats/Premises	0
5	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0
	Overall	50%

Shopping 4

Sr. No (1)	Tasks /Activity (2)	Percentage of Actual work done (as on the date of certificate) (3)
1	Excavation	100
2	Plinth	100
3	Slabs of Super Structure	50
4	Internal walls, Internal Plaster, Floorings, Doors and Windows within Flats/Premises	0
5	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0
	Overall	50%

TABLE-B
Common Areas (Internal & External Development Works) in Respect of the Registered Phase/project number

Sr. No. (1)	Common areas and Facilities (2)	Proposed (Yes/No) (3)	Percentage of Actual Work done (as on the date of certificate) (4)	Details (5)
1.	Internal Roads & Footpaths	Y	80	WBM Roads Ready
2.	Water Supply	Y	0	
3.	Sewerage (chamber, lines, Septic Tank, STP)	Y	80	Septic Tank ready
4.	Storm Water Drains	Y	100	Completed
5.	Landscaping & Tree Planting	Y	20	
6.	Street Lighting	Y	30	
7.	Community Buildings	Y	0	

Sr. No. (1)	Common areas and Facilities (2)	Proposed (Yes/No) (3)	Percentage of Actual Work done (as on the date of certificate) (4)	Details (5)
8.	Treatment and disposal of sewage and sullage water	N	-	
9.	Solid Waste management & Disposal	N	-	
10.	Water conservation/ Rain water harvesting	Y	25	
11.	Energy management	N	-	
12.	Fire protection and fire safety requirements	N	-	
13.	Electrical meter room, sub-station receiving station	N	-	
		Overall	41.70%	

Yours Faithfully,

For UB Architects

Ar. Ujwal S. Bhole
License No. CA/2010/47919



[Handwritten Signature]

Signature of Promoter
Name: Vinaykumar Parakh, Prop. Parakh Realities
Date: