



D. N. Joshi Architects, Nanded

Construction works under Maharashtra Act 2011

Architects - Mr. & Mrs. Q. B. Joshi

Office Address:

Plot No. 17, Chhatrapati Sambhaji Maharaj Road,

Nanded City - Dist. Nanded - 431002

M. No. 9217643335, 9233883335

Mail ID: dnjoshiarchitects@gmail.com

Form 1

(See Regulation 3)

ARCHITECT'S CERTIFICATE

**(To be submitted at the time of Registration of Ongoing project and for
Withdrawal of Money from Designated Account)**

Date: 01.06.2024

To

The Partners-

The Golden Heritage

S.No. 94/2/B, Near Vijay Shree Nagar,

Hole Shwane, Nanded City,

Dist. & Dist. Nanded-431002

Subject: Certificate of percentage of completion of construction work of **The Golden Heritage** during Maharashtra Registration Number **P49700029921** being developed by **The Golden Heritage**.

Re:

I, Mr. Dhananjay Narayana Joshi have undertaken assignment as Architect/ Licensed Surveyor of certifying percentage of Completion of Construction work of the **The Golden Heritage** having Maharashtra Registration Number **P49700029921** being developed by **The Golden Heritage**.

Based on site inspection, with respect to layout/each of the building/wing of the abovesaid Real Estate project, I certify that as on the date of this certificate, the percentage of work done for each of the building/wing of the Real Estate project under Maharashtra is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in table B.

Table A
The Golden Heritage Row House 3

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.05.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Reinments (if any)	100%
3	Columns (if any)	100%
4	Plinth	100%

5	Soil Fill	100%
6	State of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead and Underground Water Tanks	100%
10	Internal plumbing and external Plaster, Fire alarm, installation of services with interpenetration of the building/ wing	100%
11	Installation of Lifts, Water pumps, Jm Lighting Fittings and Equipment as per CTO MCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of clearance / CRZ, NDC Fencing to enclose Lobby / a plot/ location, Fencing of area adjacent to building/ Wing, Compensated work and all other requirements as may be required to complete the project as per specifications in agreement of title. Any other activities.	100%

Table 4
The Golden Heritage Kow House 4

Sr.No.	Task/Activity	Percentage of actual work done (As on 11.05.2024)
	(a)	(b)
1	Excavation	100%
2	Foundations (if any)	100%
3	Pillars (if any)	100%
4	Plinth	100%
5	Soil Fill	100%
6	State of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary fittings within the flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead and Underground Water Tanks	100%

10	External plumbing and external Plaster, Elevation, completion of terrace with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / L&E NCC, Finishing to entrance Lobby/s, plants Protection, Paving of area appurtenant to building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications as agreed upon at sale. Any other activities	100%

Table A

The Golden Heritage Rose House 3

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Foundation	100%
2	Basement (if any)	100%
3	Columns (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Rooms	100%
8	Sanitary Fittings Within the Flat/ Rooms	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level (overhead) and Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terrace with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / C&E NCC, Finishing to entrance Lobby/s, plants Protection, Paving of area appurtenant to building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications as agreed upon at sale. Any other activities	100%

Table A

The Gullane Heritage Row House 6

Sr. No.	Task/Activity	Percentage of actual work done (As on 31/03/2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Cellars (if any)	100%
4	Plots	100%
5	Sub Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Doorways, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts, Wells and Lobbies at each floor level overland Undergrround Water Tanks	100%
10	External plumbing and external Plaster, Guttering, completion of terraces with waterproofing of the building/wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NCC, Electrical Fittings, Mechanical Equipments Compliance to conditions of environment / C/O NCC, Finishing to entrance Lobby's, plinth Premises, Paving of area appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A

The Golden Heritage Row House?

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Foundations (if any)	100%
3	Columns (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Finishing, Doors and Windows Within Floor / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts, Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire fighting Fittings and Equipment as per CRZ NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby / s, plinth Protection, Paving of area apartment in Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A

The Golden Hinge Row House A

Sr. No	Task/Activity	Percentage of actual work done (As on 31.03.2020)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	100%
9	Staircases, Lifts, Wells and Lobby at each Floor level, overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevators, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire fighting Fittings and Equipment as per COC /NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of allotment / COC /NOC, Finishing to entrance Lobby's, glazed Protection, Paving of areas appurtenant to building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Rese House II

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Rebarwork (if any)	100%
3	Founders (if any)	100%
4	Plinth	100%
5	Wall Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts, Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing, and external Plaster, Elevation, completion of terrace with waterproofing of the building/wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per COC/NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby's, plinth Protection, Paving of area apartment in Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Res House 10

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2020)
(1)	(2)	(3)
1	Description	100%
2	Basements (If any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Full Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat / Premises	100%
8	Sanitary Fittings Within the Flat/ Premises	100%
9	Staircases, Lifts/ Wells and Lobbies at each Floor/level overhead Underground/Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of gutters with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CHO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance / Lobby/A, plinth Protection, Paving of mass apartment in Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A
The Golden Heritage Row House II

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Floors	100%
5	Roof Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Floor /Premises	100%
8	Sanitary Fixings Within the Flat/Premises	100%
9	Staircases, Lifts, Wells and Lobby at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terrace with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fixings and Equipment as per CDD NCC, Electrical Fixings, Mechanical Equipments, Compliance to cleanliness of environment / CRZ NCC, Finishing to interiors, Lobby/s, plinth Protection, Paving of areas appertaining to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 12

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(i)
1	Excavation	100%
2	Basement (Party)	100%
3	Podium (Party)	100%
4	Plinth	100%
5	Full Floor	100%
6	Slab of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Plot / Premises	100%
8	Sanitary Fittings Within the Plot/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level (vertical) Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevators, completion of terrace with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CDD NCC, Electrical Fittings, Mechanical Equipments, Compliance in condition of environment / CRZ NCC, Finishing to entrance Lobby / s, Plinth Protection, Paving of area appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 13

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Foundation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Floors	100%
5	Silt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level and/or at Underground Water Tanks	100%
10	External plumbing and external Plaster, elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NOK, Electrical fittings, Mechanical Equipments, Compliance to conditions of environment / C&E NOK, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other equipments as may be required to complete the project as per specifications in agreement of title. Any other activities.	100%

Table A

The Golden Heritage Row House 14

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Soil Elevation	100%
6	Grade of Super Structure	100%
7	Internal Walls, Internal Doors, Floorings, Doors and Windows Within Flats / Porticoes	100%
8	Secondary Fixings Within the Flat/ Porticoes	100%
9	Staircases, Lifts, Wells and Lobbies at each floor level, mechanical Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of surfaces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NOC, Electrical Fixings, Mechanical Equipments, Compliance to conditions of environment / C/O NOC, Finishing to entrance Lobby / s, plinth Protection, Paving of areas appertaining to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A
The Golden Heritage Row House 13

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Foundation (If any)	100%
3	Columns (If any)	100%
4	Plinth	100%
5	Sub Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per LFC/NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ/NOC, Finishing to entrance Lobbies, plinth Protection, Fencing of areas appurtenant to Building/Wing, Compound wall and all other equipments as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A

The Golden Heritage Bore House JB

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basements (if any)	100%
3	Pediments (if any)	100%
4	Plinth	100%
5	5th Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flats / Premises	100%
9	Staircases, Lifts Wells and Lobbies at each floor level overhead Underground Water Tanks	100%
10	External finishing and external Plaster, Elevation, completion of terraces with waterproofing of the Building/ wing	100%
11	Installation of Lites, Water pumps, Fan lighting fittings and Equipment as per LDO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / COE NOC, Finishing to entrance Lobby/s, finish Partitioning, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A
The Golden Heritage River House 17

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (Ready)	100%
3	Podiums (Ready)	100%
4	Floors	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Ceilings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flats/Premises	100%
9	Staircases, Lifts Walls and Lockers at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to modules of environment / CRZ, NOC, Handing to entrance Lobby/s, plinth Protection, Paving of access apartment in Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House (B)

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basements (Basin)	100%
3	Podiums (2 story)	100%
4	Plinth	100%
5	Fifth Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Parties, Partings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	100%
9	Staircases, Lifts, Wells and Lobbies at each floor level, overhead Underground Water Tanks	100%
10	External plastering and external Plaster, Elevation, completion of terraces with waterproofing of the building / wing.	100%
11	Installation of Lifts, Waste pumps, Fire Fighting Fittings and Equipment as per C/O NDC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / C/O NDC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas surrounding to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A
The Golden Heritage Row House D9

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(A)	(B)	(C)
1	Excavation	100%
2	Basements (if any)	100%
3	Foundations (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	External Walls, Internal Plaster, Finnings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	100%
9	Staircases, Lifts Wells and Lobby at each floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevations, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plant Protection, Draining of areas appurtenant to building/ wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 2)

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Reinforcement (R/Wing)	100%
3	Cast concrete (R/Wing)	100%
4	Plumb	100%
5	Silt floor	100%
6	Scaffolding Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/ Premises	100%
9	Staircases, Lifts Wells and Lobbies at each floor level installed. Underground Waste Tanks	100%
10	External plastering and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / C/E, NDC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Rice House 21

Sr. No.	Task/Activity	Percentage of actual work done (As on: 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Foundations (if any)	100%
3	Columns (if any)	100%
4	Roof	100%
5	5th Floor	100%
6	Slab of Super Structure	100%
7	Internal Walls, Internal Plaster, Paintings, Doors and Windows Within Floor / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobby at each Floor level (includng Underground Water Tanks)	100%
10	External plumbing and external Plaster, Dewatering, completion of services with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per COC NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CEZ / ROC, Finishing to entrance Lobby/s, plants Protection, Paving of areas appertaining to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A

The Golden Heritage Res. House II

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (if any)	60%
3	Podiums (if any)	0%
4	Plinth	0%
5	Slab Floor	0%
6	Slab of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Plots / Premises	0%
8	Sanitary Fixings Within the Plot/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fixings, Mechanical Equipments, Compliance to conditions of encroachment / CRZ NOC, Fencing to entrance Lobby/s, plinth Protection, Paving of areas appropriate to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of site. Any other activities.	0%

Table A

The Golden Heritage Home House 23

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basement (if any)	100%
3	Podium (if any)	100%
4	Plinth	100%
5	5th Floor	100%
6	Roof of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	100%
9	Staircases, Lifts Wells and Lobbies at each floor level overhead Underground Water Tanks	100%
10	External plastering and external Plaster, Elevation, completion of terrace with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/A, plinth Protection, Fencing of area adjacent to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A

The Golden Heritage Row House 24

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basement (If any)	100%
3	Columns (If any)	100%
4	Plinth	100%
5	Self Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Doors, Floorings, Doors and Windows Within Flat / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/D/NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / C/E/NOC, Finishing to entrance Lobby/s, plants Protection, Paving of areas adjacent to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A

The Gulistan Heritage Rese Project 25

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (if any)	100%
3	Plinth (if any)	100%
4	Plinth	100%
5	1st Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat /Purposes	100%
8	Sanitary Fittings Within the Flat/Purposes	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level provided Underground Water Tanks	100%
10	External plumbing and external Plaster, Excavation, completion of terrace with waterproofing of the building/wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / COT NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of area adjacent to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Bow House 28

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Structures (4 wing)	100%
3	Podiums (2 wing)	100%
4	Plinth	100%
5	Silt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts, Wells and Lobbies at each Floor level provided. Underground Water Tanks.	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CEZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appropriate to building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 27

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (If any)	100%
3	Podium (If any)	100%
4	Plinth	100%
5	Sub Floor	100%
6	State of Super Structure	100%
7	Internal Walls, Internal Roofs, Floorings, Doors and Windows Within Plot / Premises	100%
8	Sanitary Fittings Within the Plot/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO/SOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ/NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas approximate to Building/ Wing, Compound wall and all other equipments as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A

The Golden Heritage Kow Limpa 2B

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (if any)	100%
3	Grounds (if any)	100%
4	Plinth	100%
5	Self Floor	100%
6	Slab of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	100%
9	Staircases, Lifts, Wells, and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plastering and external Plaster, Elevation, completion of terrace with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CSE/ NOC, Finishing to entrance lobby /s, glass Partition, Drivng of access symetrisant in Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 29

Sl. No.	Task/Activity	Percentage of actual work item (As on 31.03.2024)
(I)	(II)	(III)
1	Excavation	100%
2	Basements (if any)	100%
3	Plinth (if any)	100%
4	Pilots	100%
5	Sub Floor	100%
6	State of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Plots / Premises	100%
8	Sanitary Fittings Within the Plot / Premises	100%
9	Staircases, Lifts, Wells and Lobby at each Floor level overhead Underground Water Tanks	100%
10	External planking and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire / Lighting Fittings and Equipment as per CDD NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby / 6 month Protection, Paving of areas appertaining to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A
The Golden Heritage Row House 30

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (1 story)	100%
3	Podiums (1 story)	100%
4	Plinth	100%
5	Silt Pond	100%
6	Grades of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Plot / Premises	100%
8	Sanitary Fixings Within the Plot/Premises	100%
9	Staircases, Lifts, Walls and Ceilings at each Floor level/ overhead Underground Water Tanks	100%
10	External plastering and external Plaster, floorings, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPD NCC, Electrical Fittings, Mechanical Equipments / Compliance to conditions of endorsement / CRZ NCC, Finishing to entrance Lobby / s, plinth Protection, Drying of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House II

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basements (If any)	100%
3	Podiums (If any)	100%
4	Pilotis	100%
5	Silt Close	100%
6	Slabs of Super Structure	100%
7	Internal walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fixings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies of each floor level, overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fixings and Equipment as per LFC/ NCC, Electrical Fixings, Mechanical Equipments, Compliance to conditions of environment / CRZ/ NCC, Finishing to entrance Lobby/ s, plinth Protection, Fixing of street apparatus to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Bore House 32

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(A)	(B)	(C)
1	Excavation	100%
2	Reinments (If any)	100%
3	Pudding (If any)	100%
4	Plinth	100%
5	Silt/Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Plastering, Doors and Windows, Window Pane / Frames	100%
8	Sanitary Fittings Within the TIA/Premium	80%
9	Staircases, Lift Wells and Lobbies at each Store level provided Underground Water Tanks	100%
10	External plastering and external Plaster, Elevation, completion of surfaces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO/CC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ/NOI, Finishing to entrance Lobby /s, plinth Protection, Drying of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	90%

Table A
The Golden Heritage Row House II

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(i)
1	Excavation	100%
2	Basement (if any)	100%
3	Columns (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Plinthings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/ Premises	60%
9	Staircases, Lift Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plastering and external Plaster, Elevation, completion of premises with waterproofing of the building/ wing	100%
11	Installation of Lids, Water pumps, Fire Fighting Fittings and Equipment as per CPC NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ, etc., Finishing to entrance Lobby/ s, plants Protection, Fencing of areas appurtenant to Building/ Wing, Compound wall and all other equipments as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A
The Golden Heritage Row House 34

Sr. No.	Task/Activity	Percentage of actual work, (in %) (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Foundation (Foot)	100%
3	Foundation (Beam)	100%
4	Roof	100%
5	Drill Floor	100%
6	Slabs of Super structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	25%
8	Sanitary Fittings Within the Flat/Premises	50%
9	Staircases, Lifts Wells and Landings at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipments as per CDD NDC, Electrical Fittings, Mechanical Equipments, Compliance to conductors of environment / CRZ NDC, Finishing to entrance Lobby / A, plinth Protection, Fencing of area appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	50%

Table A

The Golden Heritage Row House 35

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1.	Excavation	100%
2.	Basements (if any)	100%
3.	Podiums (if any)	100%
4.	Plinth	100%
5.	5th Floor	100%
6.	Staircases Structure	100%
7.	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Poomas	100%
8.	Sanitary Fittings Within the Flat/Poomas	80%
9.	Railways, Lifts Wells and Lobbies at each floor level overhead Underground Water Tanks	100%
10.	External plumbing and external Plaster, Elevators, completion of terraces with waterproofing of the building/ wing	100%
11.	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CIO NDC, Electrical Fittings, Mechanical Equipments, Compliance in conditions of environment / CRZ, NDC, Finishing to entrance Lobby's, porch Protection, Paving of area appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A
The Golden Heritage Row House 36

Sr. No.	Task/Activity	Percentage of actual work done (As on 11/03/2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basements (if any)	100%
3	Foundations (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	State of Super Structure	100%
7	Internal Wall, Internal Plaster, Floorings, Doors and Windows Within Plot / Premises	100%
8	Sanitary Fittings Within the Plot / Premises	70%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	80%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPD NCC , Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CEZ NCC, Finishing to entrance Lobby's, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	80%

Table A
The Golden Heritage Row House 51

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2023)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (Drain)	100%
3	Podium (Drain)	100%
4	Plinth	100%
5	5th Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terrace with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipments as per CRZ NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, Plinth Protection, Fencing of access appartments to Building/ Wing, Completed wall and all other requirements as may be required to complete the project as per specifications in agreement of sub. any other drawings.	80%

Table A

The Golden Heritage Bay / House 53

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basement (Ramp)	100%
3	Radiants (Ramp)	100%
4	Plinths	100%
5	1st Floor	100%
6	Slab of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Plots / Premises	100%
8	Sanitary Fittings Within the Plot / Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level, overhead Underground Water Tanks	100%
10	External plastering and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CDD NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CDD NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other equipments as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A
The Golden Heritage River House 53

Sr. No.	Task/Activity	Percentage of actual work done (As on 31-03-2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Drains/cuts (if any)	100%
3	Drainage (if any)	100%
4	Plinth	100%
5	Sub Floor	100%
6	Slabs of Super structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Plot / Perimeter	100%
8	Sanitary Fittings Within the Plot / Perimeter	100%
9	Staircases, Lift Wells and Lobby at each Floor level overhead Underground Water Tanks	80%
10	External plastering and external Plaster, Decoration, completion of terrace with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC , Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CKE NOC, Finishing to entrance Lobby/s, plinth Protection, Fencing of site/appurtenance to building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A

The Golden Heritage Row House 24

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (Ramp)	100%
3	Podium (Ramp)	25%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts, Walls and Lobbies at each floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Guttering, completion of kerbs with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPD NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of memorandum / CRZ NOC, Finishing to entrance Lobby /s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of site. Any other activities.	80%

Table A

The Golden Heritage Rose House 55

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1.	Excavation	100%
2.	Basement (If any)	100%
3.	Platform (If any)	100%
4.	Plinth	100%
5.	50% Floor	100%
6.	Roofs of Super Structure	100%
7.	Internal Walls, Internal Plaster, Finishing, Doors and Windows Within Floor /Premises	100%
8.	Sanitary Fittings Within the Flat/ Premises	100%
9.	Staircases, Lifts/ Wells and Lobbies at each Floor level provided Underground Water Tanks	100%
10.	External plumbing and external Plaster, Deviation, completion of terraces with waterproofing of the building/ wing.	100%
11.	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per LHO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ, NOC, Finishing to entrance Lobby /s, plinth Protection, Fixing of area apartment in Building/ Wing, Completed well and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 56

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (If any)	100%
3	Platforms (If any)	100%
4	Plinth	100%
5	Wall Floor	100%
6	Slab of Super Structure	100%
7	Internal Wall, Internal Plaster, Floorings, Doors and Windows Within Flat / Premises	100%
8	Sanitary Fittings Within the Flat/ Premises	50%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CIO NOC , Electrical Fittings, Mechanical Equipment, Compliance to conditions of environment / CRZ NOC, Finishing in entrance Lobby/c, plinth Protection, Paving of area adjoining to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale, Any other activities	80%

Table A

The Golden Heritage Rose House 57

Sr. No.	Task/Activity	Percentage of actual work done (As on 11/03/2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (if any)	100%
3	Foundation (if any)	100%
4	Plinth	100%
5	Sub Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/ Premises	80%
9	Staircases, Lifts, Utility and Lobbies at each floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terrace with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CIO/NCC, Electrical Fittings, Mechanical Equipment, Compliance to conditions of environment / CIZ/NCC, Finishing to entrance Lobby / s, Plinth Protection, Fencing of areas apportioned in Building/ Wing, Compound wall and all other improvements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A

The Golden Heritage Time House 38

No. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(A)	(B)	(C)
1	Excavations	100%
2	Reinforcement (Barrier)	100%
3	Foundations (RCC)	100%
4	Plinth	100%
5	Soil Floor	100%
6	Slab of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Plot / Premises	100%
8	Sanitary Fittings Within the Plot/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level, overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / OLE NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A
The Golden Heritage Key House 58

S/n No.	Task/Activity	Percentage of actual work done (As per 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Columns (If any)	100%
4	Pierth	100%
5	E&H Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Finish, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	100%
9	Stairways, Lifts Wells and Lobby's at each Floor level overhead, Underground Water Tanks	100%
10	External plumbing and external Floor, Elevators, completion of terrace with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per LIO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CEZ NOC, Paving to entrance Lobby / k, plinth Protection, Paving of main approaches to building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 60

Sr. No.	Task/Activity	Percentage of actual work done (As on 31-03-2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basements (Slab)	100%
3	Podiums (Slab)	100%
4	Plinth	100%
5	1 st Floor	100%
6	Roofs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Ceilings and Windows Within Plot / Premises	100%
8	Sanitary Fittings Within the Plot/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terrace with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CRZ-NOC, Electrical Fittings, Mechanical Equipments- Compliance to conditions of environment / CRZ-NOC Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 61

Sr. No	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Reinforcing (R ring)	100%
3	Podiums (R ring)	100%
4	Plinth	100%
5	Grill Floor	100%
6	Slab of Superstructure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/ Premises	100%
9	Staircases, Lift Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPD NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CEZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House #2

S/n. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Foundations (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Silt / Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	100%
9	Entrance, Lift Wells and Lobby at each Floor level, overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terrace with waterproofing of the building / wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NCC, Electrical Fittings, Mechanical Equipments / Compliance to condition of environment / CRE NCC, Finishing to entrance Lobby/s, plinth / Protection, Paving of open apartment in Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A
The Golden Heritage Row House 03

Sr. No	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Foundation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Sub Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	100%
9	Staircases, Lifts, Yards and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plastering and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plots Protection, Fencing or gates appertaining to Building / Wing, Compound wall and all other requirements as may be required to complete the project or per specifications in agreement of sale. Any other activities	100%

Table A
The Golden Heritage Row House-64

S/c No.	Task/Activity	Percentage of actual work done (As on 31/03/2024)
(1)	(2)	(3)
1	Backfilling	100%
2	Concrete (if any)	100%
3	Wallwork (if any)	100%
4	Plumb	(50%)
5	5th Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts, Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting fittings and Equipment as per CTO NOK, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOK, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appertaining to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Bow House #8

Sl. No.	Task/Activity	Percentage of actual work done (As on 7E.OA.2024)
(1)	(2)	(3)
1.	Excavation	100%
2.	Basements (If any)	100%
3.	Cellars (If any)	100%
4.	Plinth	100%
5.	Earth Floor	100%
6.	Slabs of Super Structure	100%
7.	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	85%
8.	Sanitary Fittings Within the Flat/Premises	50%
9.	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	30%
10.	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11.	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CHS NCC, Electrical Fittings, Mechanical Fittings, Compliance to conditions of enclosures / CR&NCC, Finishing to entrance Lobby /s, plinth Protection, Paving of areas appertaining to Building/ Wing- Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	70%

Table A
The Golden Heritage Row House 56

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (If any)	100%
3	Podium (If any)	0%
4	Plinth	100%
5	6th Floor	0%
6	Roofs of Super Structure	100%
7	Internal Walls, Internal Plaster, Skirtings, Doors and Windows Within Floor / Premises	85%
8	Sanitary Fittings Within the Flat/ Premises	10%
9	Staircases, Lifts, Wells and Lobbies at each Floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of services with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / GEP, NCC, Finishing to entrance Lobby/s, plot/ Perimeter, Paving of areas appurtenant to Building/ Wing, Compound wall and all other equipments as may be required to complete the project as per specifications in agreement of sale. Any other activities	70%

Table A

The Golden Heritage Row House #2

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basement (2 wing)	100%
3	Podiums (2 wing)	100%
4	Plinth	100%
5	Full Floor	100%
6	Slab and Super Structure	100%
7	Internal Walls Internal Plaster, Floorings, Doors and Windows Within Flat / Penthouse	50%
8	Sanitary Fittings Within the Flat/Penthouses	50%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing	100%
11	Installation of Life Water pumps, Fire Fighting Fittings and Equipment as per CIO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, Plinth Protection, Fixing of street apparatus in Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A
The Golden Heritage New House 68

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basement (2 days)	100%
3	Partitions (If any)	100%
4	Plinth	100%
5	Gall Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Doors, Floorings, Doors and Windows Within Flat / Premises	85%
8	Sanitary Fittings Within the Flat/Premises	50%
9	Staircases, Lifts, Wells and Lobbies at each Floor level, overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terrace with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / C&Z NCC, Finishing to entrance Lobby/s, plinth Protection, Drying of areas appropriate in Building/ Wing, Compound wall and all other arrangements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A
The Golden Heritage Row House #1

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basement (if any)	100%
3	Podium (if any)	100%
4	Plinth	100%
5	Silt Fill	100%
6	Slab of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Ceilings and Windows Within Flats / Premises	83%
8	Sanitary Fittings Within the Flat / Premises	50%
9	Staircases, Lifts, Walls and Lobbies of each Floor level, verandah, Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevators, completion of terraces with waterproofing of the building / wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFC NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing by entrance lobby / a, plinth Protection, Paving of access approaches to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A
The Golden Heritage Kuv House T9

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Foundations	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Sub Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Penthouses	60%
8	Sanitary Fittings Within the Flat/ Penthouses	60%
9	Staircases, Lifts Yards and Lobbies at each Floor level overhead, Underground Water Tanks	60%
10	External plastering and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	60%
11	Installation of Lamps, Water pumps, Fire Fighting Fittings and Equipment as per C/O NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / C/E NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A
The Golden Heritage Row House 71

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(A)	(B)	(C)
1	Excavation	100%
2	Reinforcement (if any)	100%
3	Pillars (if any)	100%
4	Plinth	100%
5	Silt Face	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat / Premises	60%
8	Secondary Fixings Within the Flat / Premises	60%
9	Stomones, Lifts Wells and Ladders at each Floor level overhead Underground Water Tanks	67%
10	External cladding and external Plaster, elevation, completion of facade with waterproofing of the building/ wing.	60%
11	Installation of Lifts, Water pumps, Fire fighting fittings and Equipment as per C/O NCC, Electrical Fixings, Mechanical Equipments /Completion to conditions of specification / C/O NCC, Finishing to entrance Lobby/s, plinth Protection, Painting of work appearance to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	60%

Table A
The Golden Heritage Bore House 72

Sr. No.	Task/Activity	Percentage of actual work item (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structures	100%
7	Internal Walls, Internal Plaster, Dadoings, Doors and Windows Within Flat / Premises	50%
8	Sanitary Fittings Within the Flat/Premises	30%
9	Staircases, Lifts Wells and Lobbies at each floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/Wing.	30%
11	Installation of Lifts, Water pumps, Fire fighting fittings and Equipment as per CTO/MOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ, etc., Finishing to entrance Lobby/s, plinth Protection Paving of areas appertaining to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	30%

Table A
The Golden Heritage B&B House 73

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Reinforce (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slab of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows /Walls Plaster /Finishes	50%
8	Sanitary Fittings Within the Flat/ Premises	30%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	30%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / COE NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of area appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	30%

Table A

The Golden Heritage Row House 74

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Roofs of Super Structure	100%
7	Internal Walls, Internal Partition, Floorings, Doors and Windows Within Flats / Premises	60%
8	Sanitary Fittings Within the Flats/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	10%
10	External plumbing and external Plaster, Elevators, completion of concrete with waterproofing of the building/wing.	100%
11	Installations of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFC NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Fencing of entire apartments in Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A
The Golden Heritage Row House 79

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (if any)	100%
3	Podium (if any)	100%
4	Plinth	100%
5	Sub Floor	100%
6	Slab of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Suites	60%
8	Sanitary Fittings Within the Flat / Suites	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead & Underground Water Tanks	30%
10	External plumbing and external Plaster, Elevation, completion of services with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per COC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ, NOC, Paving to entrance Lobby/s, plinth Protection, Paving of area appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A
The Golden Heritage Row House-74

No. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Soil Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Paintings, Doors and Windows Within Flat / Premises	60%
8	Secondary Fittings Within the Flat / Premises	60%
9	Staircases, Lifts, Wells and Lobbies at each Floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of trusses with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NOC, Electrical Fittings, Mechanical equipments, Compliance to conditions of environment / C/EZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of stairs, apartment in Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	60%

Table A
The Golden Heritage Rose House 77

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(A)	(B)	(C)
1	Excavation	100%
2	Basements (If any)	100%
3	Platforms (If any)	100%
4	Plinth	100%
5	Self floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows, Water Pans / Pansies	80%
8	Sanitary Fittings Within the Flat/Pantries	60%
9	Staircases, Lifts Wells and Lobby at each floor level, overhead Underground Water Tanks	20%
10	External plumbing and external Plaster, Elevators, completion of services with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per LPO/NDK, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CR/PCN, Finishing to entrance / Lobby/s, plots Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A
The Golden Heritage Bore House 28

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.12.2023)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Platforms (if any)	100%
4	Plinth	100%
5	5th Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Halls / Rooms	50%
8	Sanitary Fittings Within the Hall/ Rooms	0%
9	Staircases, Lifts Wells and Lobby at each floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per G.O. NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ, NOC, Finishing to entrance Lobby/s, fire Protection, Paving of access approaches to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	60%

Table A
The Golden Heritage Row House 79

No. / S/n	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(A)	(B)	(C)
1	Excavation	100%
2	Basement (Ramp)	100%
3	Plinth (If any)	100%
4	Plumb	100%
5	Silt / Dust	100%
6	State of Scaff Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat / Premises	60%
8	Sanitary Fittings Within the Flat / Premises	60%
9	Staircases, Lifts Wells and Lobby's at each Floor level overhead Underground Water Tanks	50%
10	External plinth and external Plaster, Elevation, completion of terrace with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NDC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ, NCC, Finishing to entrance Lobby/s, plinth Protection, Planting of ornamental in Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	65%

Table A
The Golden Heritage Res. House 80

(1) Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (if any)	100%
3	Podiums (if any)	100%
4	Finish	100%
5	Self Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts, Yards and Lobby at each floor level (external) Underground Water Tanks	100%
10	External plumbing and external Plaster, elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire fighting fittings and Equipment as per CPD NOK, Electrical fittings, Mechanical Equipment, Compliance to conditions of environment / CRZ NOK, Finishing terraces lobby/s, plinth Perimeter, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House #1

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Bill Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flats / Premises	60%
9	Staircases, Lifts, Wells and Lobby's at each Floor level, overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of kerbs etc with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fixings and Equipment as per C/O NOC, Electrical Fixings, Mechanical Equipments, Compliance in conditions of environment / CRZ NOC, Painting to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A
The Golden Heritage New House B2

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structures	100%
7	Internal Walls, Internal Floors, Plasterings, Doors and Windows Within Flats / Premises	80%
8	Sanitary Fittings Within the Flat/ Premises	10%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, The value, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / LCR/ NCC, Finishing to entrance Lobby /L, plinth Protection, Paving of areas appurtenant to building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A
The Golden Heritage Row House 03

Seq. No.	Task/Activity	Percentage of actual work done (As on 31.05.2024)
(I)	(II)	(III)
1	Location	100%
2	Basement (if any)	100%
3	Platforms (if any)	100%
4	Plinth	100%
5	Full Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	60%
8	Sanitary Fittings Within the Flat / Premises	60%
9	Staircases, Lifts, Wells and Lobbies at each Floor level overhead Underground Water Tanks	90%
10	External plastering and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per LPO NCC, Electrical Fittings, Mechanical Equipments, Completion of conditions of environment / CEZ NCC, Finishing to entrance Lobby/s, Glitch Protection, Paving of access apartment or Building / Wing, Compound wall and all other equipments as may be required to complete the project as per specifications in agreement of bids. Any other activities	60%

Table A

The Golden Heritage Row House 54

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2023)
(1)	(2)	(3)
1	Permutation	100%
2	Documents (if any)	100%
3	Contracts (if any)	100%
4	Plinth	100%
5	Sub Floor	100%
6	Slab of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	60%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts, Voids and Lobbies at each floor level structural Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per LPO/NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Fencing to entrance Lobby/s, Plinth Protection, Paving of areas appurtenant to building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	80%

Table A

The Golden Heritage Bawe House-85

Ss. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(A)	(B)	(C)
1	Excavation	100%
2	Basement (if any)	100%
3	Columns (if any)	100%
4	Roofs	100%
5	Silt Floor	100%
6	Sills of Super Structure	100%
7	Internal Wall, Internal Plaster, Floorings, Doors and Windows Within Plot / Premises	60%
8	Sanitary Fixings Within the Plot / Premises	60%
9	Retaining, Lime Walls and Lobbies at each Floor level attached Underground Water Tanks	60%
10	External plumbing and external Floor, floorings, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of lifts, Water pumps, Fire Fighting Fixings and Equipment as per CPO NOC, Electrical Fixings, Mechanical Equipments, Compliance in conditions of environment / CRZ NOC, Finishing to entrance Lobby / s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	60%

Table A
The Golden Heritage Bow House-08

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Foundations (if any)	100%
3	Columns (if any)	100%
4	Slabs	100%
5	5th Floor	100%
6	State of Super Structure	100%
7	Internal Walls, Internal Plaster, Paintings, Doors and Windows Within Flats / Premises	10%
8	Sanitary Fittings Within the Flat/Premises	10%
9	Staircases, Lifts Wells and Lobby at each Floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFG NOC , Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CFG NOC, Finishing in entrance Lobby/s, Plinth Protection, Paving of main approaches to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	10%

Table A
The Golden Heritage Row House #7

Sl. No	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basement (if any)	100%
3	Podium (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	60%
8	Sanitary Fittings Within the Flat/Units/ies	60%
9	Entrances, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Electricals, completion of services with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFC NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of access apartment in building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications as agreed upon of sub. All other activities.	40%

Table A

The Golden Heritage Res. House 68

S/n No.	Task/Activity	Percentage of actual work done (As on 31-03-2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basements (if any)	100%
3	Columns (if any)	100%
4	Plinth	100%
5	5th Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Ceilings and Windows Within Flats / Premises	60%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each floor level overhead Underground Water Tanks	50%
10	External plastering and external Plaster, Elevators, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire fighting Fittings and Equipment as per CPD-NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRF-NOC, Finishing to entrance Lobby/s, plinth Protection, Fixing of stairs appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A
The Golden Heritage Row House #3

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basements (Masonry)	100%
3	Podiums (Plumb)	100%
4	Plumb	100%
5	Self Floor	100%
6	Slab of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat / Terraces	60%
8	Sanitary Fittings Within the Flat/Terraces	60%
9	Storerooms, Lifts Wells and Lobbies at each Floor level and/or at Underground Water Tanks	50%
10	External plumbing and external Plaster, Floorings, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting fittings and Equipment as per C/O NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / C/Z NOC, Finishing to entrance Lobby/s, plaster Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A
The Golden Heritage River House 90

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Foundation (if any)	100%
3	Podium (if any)	100%
4	Plinth	100%
5	Sill Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Doors, Floorings, Doors and Windows Within Flats /Terraces	100%
8	Sanitary Fittings Within the Flat/Terrace	75%
9	Staircases, Lifts Wells and Lobbies at each floor level overhead Underground Water Tanks	75%
10	External planting and external Fences, elevations, completion of terraces with waterproofing of the building/wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NDC, Finishing to entrance Lobby/s, plotter Perfection, Paving of areas appropriate for Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	75%

Table A
The Golden Heritage Rose House 91

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavations	100%
2	Retainers (if any)	100%
3	Subsoils (if any)	100%
4	Plinth	100%
5	Earth Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/ Premises	75%
9	Staircases, Lifts Wells and Lobbies at each floor level, mechanical Underground Water Tanks	75%
10	External plumbing and external Plaster, Elevation, completion of terrace with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipments as per CPC/MCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CEE MCC, Fireproofing to entrance Lobby/s, theft Protection, Fencing of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	75%

Table A
The Golden Heritage Row House 32

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Foundations (if any)	100%
3	Podium (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of upper structure	100%
7	Internal Walls, Internal Doors, Floorings, Doors and Windows Within the Plot / Premises	100%
8	Sanitary Fittings Within the Plot/Premises	75%
9	Basement, Lifts, Walls and Ceilings on each floor level, overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of services with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO/NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ /NCR, Finishing in entrance Lobby / s, plinth Protection, Paving of areas appertaining to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	75%

Table A

The Golden Heritage Row House #1

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1.	Excavation	100%
2.	Basements (if any)	100%
3.	Columns (If any)	100%
4.	Plinth	100%
5.	2nd Floor	100%
6.	Slabs of Super Structure	100%
7.	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Plot / Premises	100%
8.	Sanitary Fittings Within the Plot / Premises	75%
9.	Staircases, Lifts Wells and Landings at each floor level overhead Underground Water Tanks	75%
10.	External plumbing and external Plaster, Elevations, completion of terraces with waterproofing of the building/ wing	100%
11.	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NCC, Electrical Fittings, Mechanical Equipments, Compliance to standards of environment / CRZ NCC, Finishing to entrance Lobby /s, plinth Protection, Paving of area, appointment in Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	72%

Table A

The Golden Heritage River House 19b

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basements (if any)	100%
3	Foundations (if any)	100%
4	Plinth	100%
5	Substructure	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Plasterings, Doors and Windows Within Floor / Premises	100%
8	Sanitary Fittings Within the Floor / Premises	70%
9	Entrances, Lifts, Wells and Lobbies at such floor level connected Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terrace with waterproofing of the building/ wing.	90%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby /s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A
The Golden Heritage Row House

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2014)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basements (if any)	100%
3	Wallings (if any)	100%
4	Plinth	100%
5	1 st Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Doorways, Doors and Windows, Within Flat / Premises	100%
8	Sanitary Fixings Within the Flat/Premises	70%
9	Staircases, Lifts, Wells and Lobbies at each floor level connected Underground Water Tanks	70%
10	External plastering and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	75%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CH/NOC, Electrical Fixings, Mechanical Equipments, Compliance to conditions of environment / CR/NOX, Finishing to entrance Lobby /s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications, in agreement of sale. Any other activities.	70%

Table A
The Golden Heritage River House 08

No. No	Task/Activity	Percentage of actual work item (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Foundations (if any)	100%
3	Pillars (if any)	100%
4	Plinth	100%
5	5th Floor	100%
6	Roof of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Portions	100%
8	Sanitary Fittings Within the Flat/ Portions	70%
9	Staircases, Lifts Wells and Lobby at each floor level overhead Underground Water Tanks	90%
10	External plumbing and external Plaster, Elevation, completion of surfaces with waterproofing of the building/ wing.	70%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CIO/WC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ / WC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications by agreement of sale. Any other activities.	70%

Table A
The Golden Heritage Row House 99

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.12.2023)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Basements (Ramp)	100%
4	Plinth	100%
5	5th Floor	100%
6	Roofs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	70%
9	Staircases, Lifts, Wells and Lobbies at each floor level overhead / Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of contract with waterproofing of the building/wing.	50%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO / NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of encumbrance / CPZ / NOC, Finishing to entrance Lobby / L, plinth Protection, Taxing of areas appurtenant to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A

The Golden Heritage Row House 100

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basement (if any)	100%
3	Foundation (if any)	100%
4	Plinth	100%
5	Soil Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	70%
9	Staircases, Lifts, Wells and Lobbies at each Floor level overhead Underground Water Tanks	10%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	50%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipments as per C/O NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ, NCC, Finishing to entrance lobby/s, plinth Protection, Fixing of access appertenance to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A
The Golden Heritage Row House 101

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.12.2023)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Self Floor	100%
6	Slab of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	70%
9	Staircases, Lifts/Wells and Lobbies at each floor level Overhead Underground Water Tanks	70%
10	External plumbing and external Plaster, Erection, completion of terraces with waterproofing of the building/wing	70%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CRO/NOC, Electrical Fittings, Mechanical Equipments, Compliance to authorities of environment / CPZ/NOC, Paving to entrance Lobby / s, Plinth Protection, Paving of area appurtenant to Building / Wing, Completion wall and all other requirements as may be required to complete the project as per specifications by agreement of sale. Any other activities.	70%

Table A

The Cladden Heritage Row House 102

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (If any)	100%
3	Podium (If any)	100%
4	Plinth	100%
5	Full Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Plot / Premises	50%
8	Sanitary Fittings Within the Plot / Premises	50%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terrace with waterproofing of the building / wing	50%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CHD NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CHD NOC, Finishing to entrance Lobby / s, plinth Protection, Tying of iron apparatuses to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	50%

Table A

The Golden Heritage Row House 303

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basement (if any)	100%
3	Foundation (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Plot / Premises	50%
8	Sanitary Fittings Within the Plot/Premises	50%
9	Staircases, Lifts Wells and Lobbies at each floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Masonry, completion of services with waterproofing of the building/wing	50%
11	Installations of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CKA NOC, Finishing to entrance Lobby / A, plinth Protection, Tying of wires, appointment in Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	50%

Table A
The Golden Heritage Row House 206

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Foundation	100%
2	Basement (If any)	100%
3	Podium (If any)	100%
4	Plinth	100%
5	8th Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Floors, Floorings, Doors and Windows Within Flats / Premises	90%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts Wells and Lobby at each Floor level overhead Underground Water Tanks	90%
10	External plumbing and external Floor, Elevators, completion of terrace with waterproofing of the building/ wing	50%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CTO NOC., Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CGO NOC, Finishing to entrance Lobby/s, glass Protection, Paving of area- apartment in Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	50%

Table A
The Golden Heritage Row House 185

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basements (2 nos)	100%
3	Podiums (0. no)	100%
4	Plinth	100%
5	Silt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Floor, Floorings, Doors and Windows, Within Plots / Premises	30%
8	Sanitary Fittings Within the Plot / Premises	50%
9	Staircases, Lifts Wells and Lobby at each floor level overhead Underground Water Tanks	50%
10	External plumbing and external Floor, Elevators, completion of terraces with water proofing of the building / wing.	50%
11	Installation of Lifts, Water pumps, Fire fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, glass Protection, Paving of area appurtenant to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of site. Any other activities.	50%

Table A

The Golden Heritage Row House III

Sr. No	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Foundations (if any)	100%
3	Podiums (if any)	100%
4	Floors	100%
5	5th Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat / Premises	50%
8	Sanitary Fittings Within the Flat/Premises	50%
9	Sanitaries, Lifts, Ponds and Lobbies at each Floor level completed Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	50%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NOK, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CSE NOK, Finishing to entrance lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	50%

Table A
The Golden Heritage Row House III

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.01.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (If any)	100%
3	Foundation (If any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slab of Super Structure	100%
7	Internal Walls Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	97%
8	Sanitary Fixings Within the Flat/Premises	50%
9	Entrances, Lifts Wells and Lobbies at each Floor level overhead / Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of exterior with waterproofing of the building/ wing	50%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFC NOC, Electrical Fittings, Mechanical Improvements, Compliance in conductance of environment / CRZ NOC, Finishing to entrance Lobby /s, plant Protection, Paving of areas, apartments in building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	50%

Table A

The Golden Heritage New House 106

Ss. No.	Task/Activity	Percentage of actual work done (As on 31.03.2020)
(1)	(2)	(3)
1	Excavation	100%
2	Groundwork (if any)	100%
3	Footings (if any)	100%
4	Plinth	100%
5	5th Floor	100%
6	Roof of Super structure	100%
7	Internal Walls, Internal Plaster, Plastering, Doors and Windows Within Flat / Premises	80%
8	Sanitary Fittings Within the Flat / Premises	50%
9	Staircases, Lifts Vally and Lobbies at each Floor level, water-nd Underground Water Tanks	80%
10	External plumbing and external Plaster, elevation, completion of terraces with waterproofing of the building/ wing	50%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / C/O NCC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compounded road and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	80%

Table A

The Golden Heritage Rose House 109

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(A)	(B)	(C)
1	Excavation	100%
2	Basements (if any)	100%
3	Footings (If any)	100%
4	Plinth	100%
5	Soft Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, External Plaster, Floorings, Doors and Windows Within Plots / Premises	50%
8	Sanitary Fittings Within the Plot/Premises	50%
9	Staircases, Lifts Wells and Ladders at each Plot and developed Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevations, completion of terraces with waterproofing of the building/ wing.	50%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CIO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, Plinth Projections, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	50%

Table A
The Golden Heritage Base House 110

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (If any)	100%
3	Podiums (If any)	100%
4	Punch	100%
5	Full Floor	100%
6	Slabs of Super Structure	50%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Main / Premises	50%
8	Sanitary Fittings Within the Flat/Premises	50%
9	Staircases, Lifts Wells and Lobby at each Floor level overhead Underground Water Tanks	30%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	30%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CDD NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NCC, Finishing to entrance Lobby /s, plinth Protection, Paving of access approaches to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications to agreement of sale. Any other activities	50%

Table A

The Golden Heritage Row House III

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Reinforcement (if any)	100%
3	Foundations (if any)	100%
4	Plinth	100%
5	Sub Floor	100%
6	Slabs of Super Structure	50%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Floor /Premises	10%
8	Sanitary Fittings Within the Flat/Toilet	10%
9	Subsidence, Lifts Wells and Lobbies at each floor level overhead Underground Water Tanks	10%
10	External plumbing and external Plaster, Elevations, completion of terraces with waterproofing of the building/ wing.	10%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipments as per CBO NKK, Electrical Fittings/ Mechanical Equipments, Compliance to ascertains of measurement / UZS NKK, Finishing of entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of title. Any other activities.	10%

Table A

The Golden Heritage Row House 111

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2023)
(1)	(2)	(3)
1	Foundation	100%
2	Basement (Floor)	100%
3	Grounds (if any)	100%
4	Plinth	100%
5	Silt Floor	100%
6	Slabs of Super Structure	80%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Gate / Premises	30%
8	Sanitary Fittings within the Gate/Premises	30%
9	Staircases, Lifts Wells and Lobbies at each floor level overhead Underground Water Tanks.	30%
10	External plastering and external Plaster, Elevations, completion of terraces with waterproofing of the building/ wing.	20%
11	Installation of Lifts, Water pumps and Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Completion of installation of environment / CRF NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of access/ driveway to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	30%

Table A
The Golden Heritage Res House 113

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basement (if any)	100%
3	Podiums (if any)	100%
4	Floor	100%
5	Slab/Roof	100%
6	Shell of Super-Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows, Window Frame/Partitions	100%
8	Sanitary Fittings Within the Plac./Toilets	50%
9	Staircases, Lifts, Walls and Lobbies at each Floor level, overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Finishing, completion of terrace with waterproofing of the building/wing	50%
11	Installation of Lftr, Water pumps, Fire Fighting Fittings and Equipment as per CRO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby /a, plinth Protection, Paving of access apartment to building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	50%

Table A

The Golden Heritage Row House 114

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2014)
(A)	(B)	(C)
1	Excavation	100%
2	Basement (if any)	100%
3	Valiums (if any)	100%
4	Plumb	100%
5	Start Floor	100%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Floor / Frames	0%
8	Sanitary Fittings Within the Flat/ Penthouses	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CRO NDC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CMZ/ NDC, Finishing to entrance Lobby / i.e. plinth Protection, Paving of area appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications to agreement of sale. Any other activities	0%

Table A
(The Golden Heritage Row House III)

Sl. No.	Task/Activity	Percentage of actual work done (As on 31/03/2024)
(I)	(II)	(III)
1	Excavation	100%
2	Foundation (if any)	100%
3	Columns (if any)	100%
4	Plinth	100%
5	Sub Floor	100%
6	Slabs of Super Structure	50%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Floor / Premises	30%
8	Sanitary Fixings Within the Flat / Premises	20%
9	Staircases, Lifts Wells and Lobbies at each floor level overhead Underground Water Tanks	10%
10	External plumbing and external Plaster, Plastering, completion of work with waterproofing of the building/ wing.	20%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipments as per C/O NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NCC, Finishing to entrance Lobby /s, plinth Protection, Paving of area appurtenant to Building/ Wing, Compromise wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	20%

Table A
The Golden Heritage Row House T18

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(A)	(B)	(C)
1	Excavation	100%
2	Basement (if any)	100%
3	Pillars (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Walls of Super Structure	80%
7	Internal Walls, Internal Plaster, Doorings, Doors and Windows Within Floor / Premises	50%
8	Sanitary Fittings Within the Flat / Premises	50%
9	Staircases, Lifts, Walls and Lobbies at each Floor level overhead Underground Water Tanks	30%
10	External plinthings and external Plaster, Elevations, completion of services with waterproofing of the building/ wing	50%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NCC, Finishing to entrance Lobby /s, plinth Protection, Paving of areas appertaining to Building /Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	50%

Table A
The Golden Heritage Row House 117

S/c No.	Task/Activity	Percentage of actual work done (As on 31/05/2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Silt Plug	100%
6	Slab of Super Structure	100%
7	Internal walls, Internal Plaster, Coverings, Doors and Windows Within Flat /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	70%
9	Staircase, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks.	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per LPC NCC, Mechanical Fittings, Mechanical Equipments, Compliance in conditions of agreement / CHZ NCC, Finishing to entrance Lobby /s, plinth Protection, Paving of areas appertaining to Building/Wing Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of all activity other activities.	70%

Table A

The Golden Heritage Show House / 18

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2020)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	70%
9	Toilets, Lits, Wells and Cottages at each floor level overhead Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CMC, NCC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of title. Any other activities.	70%

Table A

The Golden Heritage Rose House 119

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.07.2024)
(A)	(B)	(C)
1.	Excavation	100%
2.	Basement (If any)	100%
3.	Podiums (If any)	100%
4.	Plinth	100%
5.	Self Floor	100%
6.	Slabs of Super Structures	100%
7.	Internal Walls, Internal Plaster, Finings, Doors and Windows Within Parts /Floors	100%
8.	Sanitary Fittings Within the Flat/Primitives	70%
9.	Staircases, Lifts Within and Lobbies at each Floor level overhead Underground Water Tanks	70%
10.	External plumbing and external Plaster, Elevation, completion of terrace with waterproofing of the building/wing	100%
11.	Installation of Lifts, Water pumps, Fan Lighting, Fittings and Equipment as per CHO/DOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ/DOC, Finishing to entrance Lobby/A, plinth Protection, Paving of open apartments in Building/Wing, Compensated well and all other equipments as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A

The Golden Heritage Row House 120

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Foundations (if any)	100%
3	Perimeters (if any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	State of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	70%
9	Staircases, Lifts Wells and Lobbies at each floor level, overhead Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevators, completion of terraces with waterproofing of the building/wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CDD NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of agreement / C&A, NCC, Finishing to entrance Lobby/s, plinth Protection, Finishing of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	70%

Table A
The Galilee Heritage Rose House 111

Seq. No	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Reinforcement (RCC)	100%
3	Foundations (if any)	100%
4	Plinth	100%
5	Sub Floor	100%
6	State of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	70%
9	Watercans, Lits, Wells and Lobbies at each floor level overhead Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NCC, Electrical Fittings, Mechanical Equipment, Compliance to conditions of environment / CRZ, NCC, Linking to entrance Lobby /s, plinth Protection, Paving of areas appurtenant to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A
The Golden Heritage Row House 122

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(A)	(B)	(C)
1	Excavation	100%
2	Reinforcement (If any)	100%
3	Foundations (If any)	100%
4	Plinth	100%
5	Silt Floor	100%
6	Slabs of Superstructure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within flats / Premises	100%
8	Sanitaries / Fittings Within the Flat/Premises	70%
9	Staircases, Lifts Wells and Lobby's at each floor level overhead Underground Water Tanks	70%
10	External plumbing and external Plaster, elevations, completion of terraces with waterproofing of the building / wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per LFC NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CEE NCC, Finishing to entrance Lobby /s, plinth Protection, Paving of areas appurtenant to Building / Wing, Compacted soil and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A
The Golden Heritage Rose House (25)

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1.	Foundation	100%
2.	Basement (if any)	0%
3.	Platforms (if any)	0%
4.	Floors	0%
5.	Rift Floor	0%
6.	Slabs of Super Structure	0%
7.	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8.	Sanitary Fittings Within the Flat/Premises	0%
9.	Staircases, Lifts Wells and Lobbies at each floor level overhead Underground Water Tanks	0%
10.	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	0%
11.	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPCB NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ-NAL, Finishing to staircase / lobby / L, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Rose House 12a

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Foundations (if any)	0%
3	Plinth (if any)	0%
4	Plinth	0%
5	Fill/Floor	0%
6	Roofs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Plot /Premises	0%
8	Sanitary Fittings Within the Plot/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level, overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevations, completion of terrace with waterproofing of the building/wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting, Fittings and Equipment as per CDD/NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CDD, NCC, Finishing to entrance lobby/s, plinth Protection, Draining of areas appurtenant to building/Wing, Carpentry work and all other requirements as may be required to complete the project as per specifications in agreement of sale. And other activities.	0%

Table A

The Golden Heritage River House 127

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Foundations (if any)	10%
3	Podium (if any)	0%
4	Plinth	0%
5	Soil Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Doors, Floorings, Ceilings and Windows Within Plots / Premises	0%
8	Sanitary Fittings Within the Plot / Premises	0%
9	Bathrooms, Lifts, Wells and Lobbies at each floor level and/or underground Water Tanks	0%
10	External plumbing and external Paints, Elevation, completion of services with waterproofing of the building/ wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFC/NOC, Electrical Fittings, Mechanical Equipments & compliance to conditions of environment / CEC/NOC, Finishing to entrance Lobby/s, plinth Protection, Fixing of steel apparatus to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications or agreement of sale. Any other activities.	0%

Table A
The Golden Heritage Row House 129

Sr. No.	Task/Activity	Percentage of actual work done (As on 31/12/2020)
(i)	(ii)	(iii)
1	Excavation	100%
2	Foundations (if any)	0%
3	Reinforce (if any)	0%
4	Roofs	0%
5	Sub Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Doorways, Doors and Windows Ventilation Flaps / Frames	0%
8	Sanitary Fittings Within the Flat / Flats	0%
9	Staircases, Lifts, Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building / wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CDD & C. Electrical Fittings, Mechanical Equipments / Compliance to conditions of environment / CRZ, NOC, Finishing to entrance Lobby / s, plinth Protection, Paving of areas appertenant to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	0%

Table A
The Golden Heritage Rest House 129

Ss. No.	Task/Activity	Percentage of actual work done (As on 31/01/2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (if any)	0%
3	Wallwork (if any)	0%
4	Plinth	0%
5	Earthwork	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Placings, Doors and Windows Within Plot / Premises	0%
8	Sanitary Fittings Within the Plot/Premises	0%
9	Staircases, Lift Wells and Lobbies at each floor level (overhead) Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of services with waterproofing of the building/ wing.	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFC/ NCC. Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ/ NCC, Paving to entrance Lobby /s, plinth Protection, Paving of area adjacent to building/ Wing, Compound wall and all other equipments as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A
The Golden Heritage Res House L20

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Columns (if any)	0%
4	Plinth	10%
5	Silt Floor	0%
6	Slabs of Super Structure	10%
7	Internal Walls, Internal Plaster, Fixings, Doors and Windows Within Flat / Premises	10%
8	Sanitary Fixings Within the Flat/Premises	10%
9	Entrances, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Cladding, completion of terrace with waterproofing of the building/wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fixings and Equipment as per C/O NCC, Electrical Fixings, Mechanical Equipments, Compliance to conditions of environment / CEE NOC, Finishing to entrance Lobby/s, plinth Protection, Fixing of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	0%

Table A
The Golden Heritage Res/ House III

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2020)
(i)	(ii)	(iii)
1.	Excavation	100%
2.	Basements (if any)	0%
3.	Foundations (if any)	0%
4.	Plinth	0%
5.	Silt Hole	0%
6.	Slabs of Super Structure	0%
7.	Internal Walls, Internal Doors, Floorings, Doors and Windows Within Flats / Premises	0%
8.	Sanitary Fittings Within the Flat/Premises	0%
9.	Staircases, Lifts Wells and Lobbies at each floor level, overhead, Underground Water Tanks	0%
10.	External plastering and external Plaster, Elevation, completion of terrace with waterproofing of the building/ wing.	0%
11.	Installation of lifts, Water pumps, Fire Fighting Fittings and Equipment as per CDD/NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CDD/NCC, Finishing to entrance Lobby/s, plinth projection, Paving of areas adjacent to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications as per record of sale. And other activities.	0%

Table A

The Golden Heritage Row House 132

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (if any)	0%
4	Plinth	0%
5	Soil Filler	0%
6	Slabs of Super structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat /Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts, Walls and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, elevation, completion of terraces with waterproofing of the building/wing	0%
11	Installation of Lifts, Water pumps, Fire fighting Fittings and Equipment as per CPD NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CHZ NCC, Finishing to entrance Lobbies, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement in sale. Any other activities	0%

Table A
The Golden Heritage Row House 133

Sr. No.	Task/Activity	Percentage of actual work done (As on 11.05.2024)
(A)	(B)	(C)
1	Foundation	100%
2	Basement (2 m/s)	0%
3	Plinth (1 m/s)	0%
4	Plinth	0%
5	Self Plinth	0%
6	Frame of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat / Suites	0%
8	Sanitary Fittings Within the Flat / Suites	0%
9	Staircase, Lifts, Wells and Lobbies at each floor level and/or underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NDC / Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / C/O NDC, Finishing to entrance Lobby / a, plinth Protection, Paving of area appurtenant to building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale, Any other activities.	0%

Table A

The Golden Heritage Row House/114

Sn. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basement (if any)	0%
3	Foundation (if any)	0%
4	Plinth	0%
5	1st Floor	0%
6	Slabs at Super structure	0%
7	Internal Walls, Internal Plaster, Finishing, Doors and Windows Within Flats / Terrace	0%
8	Sanitary Fixings Within the Flat/Terrace	0%
9	Staircase, Lifts, Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Finishing, completion of terraces with waterproofing of the building / wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CIO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance lobby/lc, pinto Protection, Paving of areas appertaining to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House L&T

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basement (Plumb)	0%
3	Wallwork (Plumb)	0%
4	Plumb	0%
5	Rift Floor	0%
6	Sole of Super Structure	0%
7	Internal Wall/ Internal Plaster, Plastering, Doors and Windows Within Date / Provision	0%
8	Sanitary Fittings Within the Flat/ Common	0%
9	Staircase, Lift Well and Lobbies at each Floor level, overhead Underground Water Tanks	0%
10	External planking and external Plaster, Dewater, completion of basement with waterproofing of the building/wing.	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CHQ NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CHQ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of access approach to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A
The Golden Heritage Row House 110

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Foundation (If any)	4%
3	Pylar/Column (If any)	0%
4	Column	0%
5	Sill Floor	0%
6	Slab of Super Structure	0%
7	Internal Walls, Internal Partition, Floorings, Doors and Windows Within Flat / Flats/units	0%
8	Sanitary Fittings Within the Flat / Flats/units	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Roofs. Elevation completion of terraces with waterproofing of the building/ wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NCC, Holding to ensure liability /s, public Protection, Fencing of access appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications as agreement of sale. Any other activities	0%

Table A

The Golden Heritage Rese Home 137

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Foundation (2 story)	0%
3	Foundation (3 story)	0%
4	Block	0%
5	Roof Slab	0%
6	Slab of Super-Structure	0%
7	Internal Wall, Internal Plaster, Floorings, Doors and Windows Within Flats / Porticoes	0%
8	Boundary Finings Within the Flats / Porticoes	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level, overhead Underground Water Tanks	0%
10	External plastering and external Plaster, elevation, completion of terrace with waterproofing of the building / wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per EPO NOC, Electrical fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby / a, plinth Protection, Paving of area surrounding to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A
The Golden Hastings Row House Ltd

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basements (if any)	0%
3	Basement (if any)	0%
4	Plinth	0%
5	Silt Pond	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fixings Within the Flat / Premises	0%
9	Staircases, Lifts, Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Electrical, completion of terraces with waterproofing of the building / wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fixings and Equipment as per C/O NOC, Electrical Fixings, Mechanical Equipments, Compliance to conditions of environment / CR2 NOC, Finishing to entrance Lobby / s, plinth Finishing, Facing of waste appurtenances in Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	0%

Table A
The Golden Heritage Row House 139

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.05.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Reinforcement (If any)	0%
3	Formwork (If any)	0%
4	Plinth	10%
5	Gilt Floor	0%
6	Slab of Super Structure	0%
7	Internal Walls, Internal Cladding, Floorings, Doors and Windows Within Floor / Premises	0%
8	Sanitary Fittings Within the Flat / Premises	0%
9	Staircases, Lifts Wells and Lobbies at each floor level, overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building / wing.	0%
11	Installation of Lifts, Water pumps, Fire Fighting, Pumps and Equipment as per CDD/NCC, Electrical fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NCC, Finishing to entrance Lobby / s, plinth Protection, Paving of road approach to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A
The Golden Heritage Row House Ltd

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.05.2024)
(1)	(2)	(3)
1	Foundation	100%
2	Basement (If any)	0%
3	Podium (If any)	0%
4	Floors	0%
5	Rail Floor	0%
6	Floors of Super Structure	0%
7	Internal Walls, Internal Partitions, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fixings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plastering and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fixings and Equipment as per COC/NOC, Electrical Fixings, Mechanical Equipments, Compliance to conditions of environment / CR2 NOC, Finishing to entrance Lobby / n, plinth Protection, Paving of area appurtenant to Building/Wing, Completed wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House 141

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (if any)	0%
4	Plinth	0%
5	Slab Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Floor / Premises	0%
8	Sanitary Fittings Within the Floor/Premises	0%
9	Staircases, Lifts, Walls and Lobbies at each Floor level, mechanical, Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevations, completion of services with waterproofing of the building/wing.	0%
11	Installation of LIFT, Water pumps, Fire Fighting Fittings and Equipment as per CPD NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CPD NOC, Finishing to entrance, Lobby /A, plinth Protection, Fencing of area appurtenant to building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House 142

Ser. No.	Task/Activity	Percentage of actual work done (As on 31.03.2020)
(1)	(2)	(3)
1	Excavation	100%
2	Foundation (If any)	0%
3	Perimeter (If any)	0%
4	Plinth	0%
5	1st Floor	0%
6	Slab of Super Structure	0%
7	Internal Walls, Internal Plaster, Paintings, Doors and Windows Within Plot / Premises	0%
8	Sanitary Fittings Within the Plot Premises	0%
9	Staircases, Lifts Wells and Corridors at each Floor level overhead Underground/Water Tanks	0%
10	External plastering and external Plaster, Elevations, Completion of services with waterproofing of the building/ wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFI NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NCC, Fencing to entrance lobby / a, plinth Protection, Paving of main approach to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications or agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House (43)

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basement (Floor)	10%
3	Plinth (Floor)	45%
4	First	0%
5	5th Floor	0%
6	Slab of Super Structure	0%
7	Internal Walls, Internal Plaster, Finishing, Doors and Windows Within Room / Premises	10%
8	Sanitary Fixings Within the Flat / Premises	0%
9	Sanitation, Lifts, Water and Exhaust at each floor level overhead	0%
10	Underground Water Tanks	10%
11	External plumbing and external Plaster, Elevators, completion of terraces with waterproofing of the building/wing.	0%
12	Installation of Lifts, Water pumps, Fire Fighting, Fittings and Equipment as per CPG NCC, Electrical Fittings, Mechanical Equipment, Compliance to completion of environment / Civil NCC, Finishing to entrance Lobby / 5, glass Partition, Paving of area adjacent to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A:

The Golden Heritage Rest House 24

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.03.2024)
(i)	(ii)	(iii)
1	Conservation	100%
2	Plasterwork (if any)	0%
3	Paintwork (if any)	0%
4	Plumb	0%
5	Silt Filter	0%
6	Slabs or Super Structure	0%
7	Internal Work, Internal Plaster, Floorings, Doors and Windows Within Hall / Premises	0%
8	Sanitary fittings within the Hall/Premises	0%
9	Staircase, Lifts Wells and Lobbies at each floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terrace with waterproofing of the building/wing.	0%
11	Installation of Lifts, Water pump, Fire Fighting fittings and Equipment as per CTC NDC, Electrical fittings, Mechanical Equipment, Compliance to condition of environment / CTC NDC, Fencing to entrance Lobby / s, plants/Protections, Fencing of area appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. And other activities	0%

Table A
The Golden Heritage Rose House 145

Sr. No.	Task/Activity	Percentage of actual work done (As on: 31.03.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (if any)	0%
4	Plinth	0%
5	Sub Floor	0%
6	Shells of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fixings Within the Flat / Premises	0%
9	Structures, Lifts, Wells and Lobbies at each floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building / wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipments as per C/FD NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CGP, NOC, Finishing to entrance Lobby / s, plinth Protection, Fixing of areas appertenant to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of bids. Any other activities	0%

Table 3

Common Areas (Internal & External Development Work) in respect of the registered phase.
Project number:

(1) S. No.	(2) Common areas and facilities, Amenities	(3) Proposed (Yes/No)	(4) Percentage of Actual Work Done (As on 01.03.2024)	(5) Details
(6)	(7)	(8)	(9)	(10)
1.	Internal Roads and Footpaths	Yes	50%	Paved Roads
2.	Water Supply	Yes	30%	Water Connection Pipeline
3.	Sewerage (Chamber, Lines, Septic Tank, STP)	Yes	30%	Septic Tank With Soak Pit
4.	Storm Water Drain	No	0%	NA
5.	Landscaping & Tree Planting	Yes	0%	Only Tree Planting in Club House Area
6.	Street Lighting	Yes	0%	NA
7.	Community Buildings	No	0%	NA
8.	Treatment and Disposal of Sewage and sullage water	No	0%	NA
9.	Solid Waste Management & Disposal	No	0%	NA
10.	Water Conservation/Rain Water Harvesting	Yes	30%	Only Rain Water Harvesting
11.	Energy Management	No	0%	NA
12.	Fire Protection And Fire Safety Requirements	No	0%	NA
13.	Electrical mains room, Sub-Station, Receiving station	No	0%	NA
14.	Open Parking	No	0%	NA
15.	Entrance Gate With Security Cabin	Yes	60%	NA
16.	Aggregate area of recreational Open Space	Yes	25%	Club House

Yours Faithfully



MR. DHANALAY NARENDRA JOSHI

(License No. _____)

Agreed and Accepted by

Mr. The Golden Heritage

MR. THE GOLDEN HERITAGE

PARTNER

Name: Mr. Anand Lalitlal Jais

Designation: Partner

Date: 01.08.2024