



D.N. Joshi Architects, Nandurbar

Chartered Members (M.A. 7085) (M.A. 7086) (M.A. 7087) (M.A. 7088)

Architects, Interior Designers, Vastu Experts

Office Address:

Plot no-17, Jyotiba Karmacharya Society,

Nandurbar dist. Nandurbar-425412

Phone-9212549535, 9405997199

Mail id- dnjoshi2@yahoo.co.in

Form 1

(See Regulation 3)

ARCHITECT'S CERTIFICATE

**(To be submitted at the time of Registration of Ongoing project and for
Withdrawal of Money from Designated Account)**

Date: 08.08.2024

To:

The Partners,

The Golden Heritage

S. No. 94/2/B, Near Vijay Street Nagar,

Hole Shivaj, Nandurbar.

Tal. & Dist. Nandurbar-425412

Subject: Certificate of percentage of completion of construction work of The Golden Heritage having Maharashtra Registration Number P49700029921 being developed by The Golden Heritage.

Sir,

I, Mr. Eshanraj Narendra Joshi have undertaken assignment as Architect/Licensed Supervisor of certifying percentage of Completion of Construction work of the **The Golden Heritage** having Maharashtra Registration Number **P49700029921** being developed by **The Golden Heritage**.

Based on site inspection with respect to layout/each of the Building/Wing of the aforesaid Real Estate project, I certify that as on the date of this certificate, the percentage of work done for each of the Building/Wing of the Real Estate project under Maharashtra is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in table B.



Table A
The Golden Heritage Row House 3

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (If any)	100%
3	Columns (If any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CR2 NOC, Finishing to entrance Lobby / Split level section, Paving of area appertinent to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Form 1
(See Regulation 3)
ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing project and for
Withdrawal of Money from Designated Account)

Date 18/08/2024

To,
The Partners,
The Golden Heritage
S.No. 94/2/B, Near Vapey Shree Nagar,
Bale Shiwari, Nandurbar,
Tal. & Dist. Nandurbar-425411

Subject: Certificate of percentage of completion of construction work of **The Golden Heritage** having Maha RERA Registration Number **P49700029921** being developed by **The Golden Heritage**.

Sd/-

I, **Mr. Dhnanjay Narendra Joshi** have undertaken assignment as Architect/Licensed Surveyor of verifying percentage of Completion of Construction work of the **The Golden Heritage** having MahaRERA Registration Number **P49700029921** being developed by **The Golden Heritage**.

Based on site inspection, with respect to layout/ each of the building/ wing of the aforesaid Real Estate project, I certify that as on the date of this certificate, the percentage of work done for each of the building/ wing of the Real Estate project under MahaRERA is as per table A herein below. The percentage of the work executed with respect to each of the category of the entire phase is detailed in table B.

Table A
The Golden Heritage Row House 3

Sr. No.	Task/Activity	Percentage of actual work done (As on 30/06/2024)
(1)	(2)	(3)
1	Excavation	100%
2	Foundations (If any)	100%
3	Columns (If any)	100%
4	Plinth	100%

5	Self Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing,	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipments as per CPC/NOC, Electrical Fittings, Mechanical Equipments, Compliance in conditions of environment / CRZ, NOC, Finishing to entrance Lobby /w. fire Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 6

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Retenments (If any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Self Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each floor level overhead Underground Water Tanks	100%

10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby /s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 3

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Cellars (if any)	100%
4	Plinth	100%
5	Sub-Floor	100%
6	Slabs of Super Structure :	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Boundary Fillings Within the Flat/ Premises	100%
9	Entrances, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby /s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 6

Sl. No.	Task/Activity	Percentage of actual work done (As on 30/06/2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Still Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Floor, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Raistraces, Lifts Wells and Lobbies at each floor level, overhead Underground Water Tanks	100%
10	External plastering and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CRZ NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of area appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 7

Sr. No.	Task/Activity	Percentage of actual work done (As on 31/06/2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (If any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Sub Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts, Walls and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFS/NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ/NOC, Finishing to entrance Lobby/s, Plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House B

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each floor level overlaid Underground Water Tanks	100%
10	External plumbing and external Plaster, Dewatering, completion of terrace with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting, Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale, Any other activities.	100%

Table A
The Golden Heritage Base House 9

Sr.No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Columns (if any)	100%
4	Plinth	100%
5	Soil Floor	100%
6	Roofs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Certery Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	General plumbing and external Plaster, Elevation, completion of formers with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance in conditions of environment / CRZ NOC, Finishing to entrance Lobby / s, plinth Protection, Fixing of main apparatus in Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 10

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (If any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	2nd Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Fixings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of services with waterproofing of the building / wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPE NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of encroachment / CRZ NOC, Finishing to entrance Lobby / A, plinth, Protection, Paving of 2m x 4m apartment to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Raw House II

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Foundations (If any)	100%
3	Pediments (If any)	100%
4	Plinth	100%
5	Soil Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Finishing, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies of each Floor level overhead / Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of Services with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipments as per C/O NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / URZ/ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale, Any other activities.	100%

Table A

The Golden Heritage Row House 32

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (Masonry)	100%
3	Podiums (Masonry)	100%
4	Floors	100%
5	Self Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	100%
9	Elevators, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per DCC/ NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ/ NCC, Finishing to entrance Lobby/s, Glazing Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A

The Golden Herings Row House-13

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Floors	100%
5	Roof Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	100%
9	Staircases, Lifts, Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terrace with water proofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / C/O NCC, Finishing to entrance Lobby/s, plinth Protection, Paving of access apartment in Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 34

Sl. No.	Task/Activity	Percentage of total work done (As on 30.06.2024)
(I)	(II)	(III)
1	Excavation	100%
2	Basements (If any)	100%
3	Foundations (If any)	100%
4	Plinth	100%
5	Sub-Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Floor / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead, Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terrace with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC - Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/A, plinth Perimeter, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A

The Golden Heritage Row House 15

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (If any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	5th Floor	100%
6	Roofs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terrace with waterproofing of the building/Wing	100%
11	Installation of Lifts/Water pumps, Fire Fighting Fittings and Equipment as per CBO/SOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ, NDC, Finishing to entrance Lobby/s, plinth Protection, Paving of area appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 16

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Reinments (If any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Slit Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lockers at each Floor level overhead / Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Waste pumps, Fire Fighting Fittings and Equipment as per CBO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / C&E NOC, Polishing to entrance Lobby/s, plinth Protection, Paving of access approach to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A
The Golden Heritage Row House 17

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Radiators (if any)	100%
4	Plinth	100%
5	Wall Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Escalators, Lifts, Walls and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CEZ NCC, Raining in entrance Lobby / a. plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 18

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Sub Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Stairways, Lifts, Walls and Lobbies at each floor level, overhead Underground Water Tanks.	100%
10	External plumbing, and external Plaster, illumination, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO-NOC, Electrical Fittings, Mechanical Equipments, Compliance in conditions of environment / CRZ-NOC, Finishing to entrance Lobby/a, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of said. Any other activities.	100%

Table A
The Golden Heritage Row House 18

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Reservoirs (if any)	100%
3	Pillars (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevators, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire fighting Fittings and Equipment as per CFD NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 2D

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.06.2023)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (If any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Silt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level Overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/Wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CEO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/a, Plinth Protection, Paving of area appertenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House II

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Reinments (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Roofs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Graces and Windows Within Plot / Premises	100%
8	Sanitary Fittings Within the Plot / Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level and/or at Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the Building / wing.	100%
11	Installation of Lifts, Water pumps, Fire Piping, Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Res House 32

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.05.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podrooms (if any)	0%
4	Plinth	0%
5	Sub Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flats / Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	Potential plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	0%
11	Installation of Lifts, Water pumps, Fire Fighting, Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CR2, NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of area adjacent to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	0%

Table A
The Golden Heritage Row House 23

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Sub Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	100%
9	Staircases, Lifts Wells and Lobbies at each floor level, overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevators, completion of terrace with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CEO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/A, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 24

Sl. No	Task/Activity	Percentage of actual work done (As on 30.06.2023)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircase, Lifts Wells and Lobbies at each floor level overhead / Underground /Water Tanks	100%
10	External plumbing and external Plaster, Plastering, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per GPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A
The Golden Heritage Row House 25

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Silt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building / wing	100%
11	Installation of Lifts, Water pumps, Fire lighting fittings and Equipment as per C/O NOC, Electrical fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Plastering to entrance lobby / s, plinth Protection, Paving of areas appurtenant to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A
The Golden Heritage Row House 28

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Slit Floor	100%
6	Slab of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Landings at each Floor level overhead Loadings and Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CTC/NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CSE, NOC, Finishing to entrance Lobby/A, plinth Protection, Paving of areas appurtenant to building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A
The Golden Harlinge Row House 27

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (if any)	100%
3	Podium (if any)	100%
4	Plinth	100%
5	Soil Floor	100%
6	Slab of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead / Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CDD NCC , Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NCC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appertinent to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 28

Sr. No.	Task/Activity	Percentage of actual work done (As on 30/06/2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, External Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Secondary Fixings Within the Flat/Premises	100%
9	Streets, Lift Wells and Lobbies at each Floor level overhead Underground Water Tanks.	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipment, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Drivng of area appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 29

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Soil Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevations, completion of terraces with waterproofing of the building/wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CDD NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CEE NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appertaining to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House III

Sr. No	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(i)	(ii)	(iii)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Soil Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each floor level overhead / Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, glinth Protection, Paving of areas appurtenant to building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A
The Golden Heritage Row House 31

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Subs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Rate / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Reservoirs, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CHD NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NCC, Finishing in entrance lobby / a, plinth Protection, Paving of areas appertenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 32

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (If any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Sub Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	80%
8	Sanitary Fixings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overland Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NOC , Electrical Fittings, Mechanical Equipments /Compliance to conditions of environment / CR2 NOC/ Finishing to entrance Lobby/s, Plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A

The Golden Heritage Row House 33

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Reinforcement (slab)	100%
3	Roofing (Easy)	100%
4	Plinth	100%
5	Soil Floor	100%
6	Slab of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat / Premises	100%
8	Sanitary Fittings Within the Flat/ Premises	80%
9	Staircases, Lift Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NOC, Electrical fittings, Mechanical Equipment, Compliance to conditions of environment / CRZ, NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of area appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale, Any other activities	80%

Table A

The Golden Heritage Row House 34

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (If any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Base /Premises	100%
8	Sanitary Fittings Within the Flat /Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing in entrance Lobby/s, Plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	80%

Table A
The Golden Heritage Row House 33

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Soil Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	40%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CTO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	90%

Table A
The Golden Heritage Row House 35

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1.	Excavation	100%
2.	Basements (if any)	100%
3.	Podiums (if any)	100%
4.	Plinth	100%
5.	Slab Floor	100%
6.	Slabs of Super Structure	100%
7.	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8.	Sanitary Fittings Within the Flat/Premises	80%
9.	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10.	External plumbing and external Plaster, Plastering, completion of terraces with waterproofing of the building / wing.	100%
11.	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFD / NCC, Electrical Fittings, Mechanical Equipments, Compliance in conditions of environment / CGZ / OC, Finishing to entrance Lobby / s, Plinth Protection, Paving of area appurtenant to Building / Wing, Compensated wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	85%

Table A

The Golden Heritage Row House 51

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Sub Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fixings Within the Flat / Premises	80%
9	Staircases, Lifts Wells and Lobbies at each floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevations, completion of terraces with waterproofing of the building / wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CR/ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A

The Golden Heritage Row House-52

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Finish of Super Structure	100%
7	Internal Walls (Internal Partition), Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fixings Within the Flat/Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Passes; Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fixings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/e, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	60%

Table A

The Golden Heritage Bay House 53

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Built Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Partitions, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fixings Within the Flat / Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of services with waterproofing of the building / wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fixings and Equipments as per CFD NOC, Electrical Fixings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth protection, Paving of areas appertaining to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	80%

Table A

The Golden Heritage Row House 54

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Pediments (if any)	100%
4	Plinth	100%
5	5th Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	90%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting, Fittings and Equipment as per CPO/NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ/NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A

The Golden Heritage Row House 55

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Pinth	100%
5	Slit Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	100%
9	Staircases, Lifts, Walls and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ / NCC, Finishing to entrance Lobby/s, pinth Protection, Paving of area appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of site, Any other activities	100%

Table A

The Golden Heritage Row House 56

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Soil Floor	100%
6	Slab and Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts Walls and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing	100%
11	Installation of Lifts /Water pumps, Fire Fighting Fittings and Equipment as per C/O NOC., Electrical Fittings, Mechanical Equipment, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, Plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A
The Golden Heritage Row House 37

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Bracements (if any)	100%
3	Podiums (if any)	100%
4	Drifts	100%
5	Soil Plant	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NOC, Electrical Fittings, Mechanical Equipments, Compliance in conditions of environment / CRZ NOC, Paving to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A
The Golden Heritage Row House 58

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Silt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ/NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of area appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A
The Golden Heritage Row House 99

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Foundations (if any)	100%
3	Columns (if any)	100%
4	Plinth	100%
5	Soil Back	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Elevators, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevations, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NDC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 60

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2023)
(1)	(2)	(3)
1	Excavation	100%
2	Documents (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	5th Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CEO NOC. Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, Plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in Agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House #1

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Columns (if any)	100%
4	Plinth	100%
5	Full Floor	100%
6	State of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per COC NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby's, plinth Perimeter, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A

The Golden Heritage Row House 62

Sr. No.	Task/Activity	Percentage of actual work done (As per 30.06.2024)
(1)	(2)	(3)
1	Excavations	100%
2	Basements (If any)	100%
3	Pediments (If any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/ Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CEO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, Plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 63

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Receptors (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Felt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/ Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical fittings, Mechanical Equipments, Compliance to conditions of environment / ERZ NOC, Finishing to entrance Lobby /s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A

The Golden Heritage Row House 64

Sr. No	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Self Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lift Wells and Lobbies at each Floor level, overhead & Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation completion of terraces with waterproofing of the building/wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per EPC NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of endorsement / CRZ NOC, Finishing to entrance Lobby/s, glinth Protection, Fencing of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A
The Golden Heritage Row House 95

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Piling	100%
5	Slab Floor	100%
6	Slab of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts Yells and Lobbies at each Floor level overhead Underground Water Tanks	80%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of area appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A

The Golden Heritage Row House 46

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Self Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts Walls and Lobbies at each Floor level overhead Underground Water Tanks	80%
10	External painting and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPD NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing in external Lobby / s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A
The Golden Heritage Row House 67

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Columns (if any)	100%
4	Plinth	100%
5	Sub Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	85%
9	Rainwater, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	60%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CEZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of roads appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A

The Golden Heritage Row House 68

Sr.No.	Task/Activity	Percentage of actual work done (As on 30.06.2022)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	5th Floor	100%
6	Slab of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fixings Within the Flat/ Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	80%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fixings and Equipment as per CEO NOC, Electrical Fixings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A
The Golden Heritage Row House 69

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Floor	100%
5	Silt Floor	100%
6	State of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level over/under Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing,	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFU-NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CR2 NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compounded wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 70

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Site Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobby at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPC/NOC, Electrical Fittings, Mechanical Equipments / Compliance to conditions of environment / CRZ/ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications or agreement of side. Any other activities.	100%

Table A

The Golden Heritage Row House 71

Sr.No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Reinforcement (if any)	100%
3	Plumbing (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls (Internal Plaster, Floorings, Doors and Windows Within Flats / Premises)	100%
8	Sanitary Fittings Within the Flat / Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building / wing	100%
11	Installation of Lids, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments Complying to conditions of environment / CRZ NOC, Finishing to entrance Lobby / s, plinth Protection, Paving of areas appurtenant to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	100%

Table A

The Golden Heritage Row House 72

Sr. No	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Sanatoria (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Bill Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, External Plaster, Floorings, Doors and Windows Within Flats / Premises	60%
8	Sanitary Fittings Within the Flat/Premises	30%
9	Staircases, Lifts, Wells and Lobbies at each Floor level overhead Underground Water Tanks	30%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	50%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C&O/NOX, Electrical Fittings, Mechanical Equipments, Compliance in conditions of environment / C&O/NOX, Finishing to entrance Lobby/x; plinth Protection, Paving of areas appurtenant to building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	30%

Table A
The Golden Heritage Row House 73

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Foundations (if any)	100%
4	Plinth	100%
5	Soil Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	60%
8	Sanitary Fittings Within the Flat/ Premises	30%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terrace with water-proofing of the building/ wing	30%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	50%

Table-A

The Golden Heritage Row House 34

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	60%
8	Sanitary Fittings Within the Flats/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor-level overhead Underground Water Tanks	30%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CDD NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ, NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas adjacent to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A

The Golden Heritage Row House 73

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2020)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Foundations (if any)	100%
4	Plinth	100%
5	Soil Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	60%
8	Sanitary Fixings Within the Flat/ Premises	60%
9	Roadways, Lifts, Wells and Lobbies at each floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of lifts, Water pumps, Fire Fighting Fixings and Equipment as per CPO NOC , Electrical Fixings, Mechanical Equipments, Compliance to conditions of environment / CRP NOC, Finishing to entrance Lobby/a, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A

The Golden Heritage Row House 76

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1.	Excavation	100%
2.	Foundation (Ramp)	100%
3.	Padstone (Ramp)	100%
4.	Plinth	100%
5.	Sub Floor	100%
6.	Slabs of Super Structure	100%
7.	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	60%
8.	Sanitary Fixings Within the Flat/Premises	40%
9.	Subcases, Lifts Walls and Lobbies at each Floor level overhead Underground Water Tanks	50%
10.	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11.	Installation of Lifts, Water pumps, Fire Fighting Fixings and Equipment as per CPO/NOC. Electrical Fixings, Mechanical Equipments, Compliance in conditions of environment / CRZ NOC, Finishing in entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A
The Golden Heritage Row House 77

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.6.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Pediments (if any)	100%
4	Plinth	100%
5	Sub Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	60%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPD NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NCC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	60%

Table A
The Golden Heritage Row House 78

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(A)	(B)	(C)
1	Excavation	100%
2	Basements (If any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	10%
8	Sanitary Fittings Within the Flats/Premises	50%
9	Staircases, Lifts Wells and Lobbies on each floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts /Water pumps /Fire Fighting Fittings and Equipment as per CPD NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	60%

Table A
The Golden Heritage Raw House 79

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (If any)	100%
3	Pediments (If any)	100%
4	Plinth	100%
5	Bill Floor	100%
6	Slabs of Super structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	70%
8	Sanitary Fittings Within the Flat / Premises	40%
9	Staircases, Lifts Wells and Lobbies at each floor level, overhead Underground Water Tanks	50%
10	Internal plumbing and external Plaster, Elevation, completion of terraces with water-proofing of the building / wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC. Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC. Finishing in entrance Lobby/s, plinth Protection, Paving of area appurtenant to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A

The Golden Heritage Row House 80

Sr. No.	Task/Activity	Percentage of actual work done (As on 30/06/2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slab of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Suites	100%
8	Sanitary Fittings Within the Flat/Suites	100%
9	Staircases, Lifts, Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of services with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFC NDC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NDC, Finishing to entrance Lobby / a. plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A
The Golden Heritage Row House #1

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Silt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Doors, Floorings, Doors and Windows Within Flat / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby / a, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A

The Golden Heritage Row House 82

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Reinforcement (if any)	100%
3	Foundations (if any)	100%
4	Plinth	100%
5	5th Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Floor, Floorings, Doors and Windows Within Flats / Premises	80%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	30%
10	External planking and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO/NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CQ/NCC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	30%

Table A

The Golden Heritage Row House 83

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2020)
(1)	(2)	(3)
1	Excavation	100%
2	Reinforcement (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	5th Floor	100%
6	State of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat / Premises	60%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevations, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	60%

Table A

The Golden Heritage Row House S4

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Foundations (RCC)	100%
3	Piers (RCC)	100%
4	Plinth	100%
5	Soil Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats/Premises	90%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Sanitation, Lift Wells and Lobbies at each Floor level overhead Underground Water Tanks	50%
10	External plinching and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts /Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, Plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	60%

Table A
The Golden Heritage Row House #5

Sr. No	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Floors	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	90%
8	Sanitary Fittings Within the Flat / Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level, overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to condition of environment / CRZ NOC, Finishing to entrance Lobby/s, plant Protection, Fencing of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A

The Golden Heritage Row House 86

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Reinments (if any)	100%
3	Foundations (if any)	100%
4	Plinth	100%
5	Sub Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	80%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Rampways, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	38%
10	External plastering and external Plaster, Elevation, completion of terrace with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A

The Golden Heritage Row House 89

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Slit Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	80%
8	Sanitary Fittings Within the Flat/ Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Waste Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building / wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC , Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/a, plinth Protection, Paving of areas appurtenant to building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A

The Golden Heritage Row House 88

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (if any)	100%
3	Podiums (if any)	100%
4	Piloth	100%
5	Slit Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	50%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each floor level overhead Underground Water Tanks	50%
10	External plastering and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting fittings and equipment as per EFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, piloth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale, Any other activities	60%

Table A

The Golden Heritage Row House 89

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (If any)	100%
3	Foundations (If any)	100%
4	Plinth	100%
5	Self Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls/ Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	80%
8	Sanitary Fittings Within the Flat/ Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of services with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Protege and Equipment as per C/O NOC , Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby /s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A

The Golden Heritage Row House-98

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1.	Excavation	100%
2.	Basements (if any)	100%
3.	Podiums (if any)	100%
4.	Plinth	100%
5.	Stilt Floor	100%
6.	Slab of Super Structure	100%
7.	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8.	Sanitary Fittings Within the Flat / Premises	75%
9.	Staircases, Lifts Wells and Lobbies at each Floor level overhead, Underground Water Tanks	75%
10.	External plumbing and external Plaster, Elevation, completion of terrace with waterproofing of the building/ wing.	100%
11.	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby / s, plinth Protection, Paving of around apartment in Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	75%

Table A
The Golden Heritage New House 93

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Silt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Finishing, Doors and Windows Within Flat / Premises	90%
8	Sanitary Fittings Within the Flat/Premises	70%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	75%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CDD NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas apportioned to building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	75%

Table A
The Golden Heritage Row House 92

Sr. No	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	5th Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Clad / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	75%
9	Staircases, Lifts Wells and Lobbies at each Floor level including Underground Water Tanks	75%
10	External plumbing and external Plaster, Finishing, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby /s, Plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	75%

Table A

The Golden Heritage Row House 93

Sr.No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Sub Floor	100%
6	Slab of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	75%
9	Staircases, Lifts Wells and Lobbies at each floor level overhead Underground Water Tanks	75%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the Building/Wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compounded wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	75%

Table A
The Golden Heritage Row House W

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Full Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Stairways, Lifts, Walls and Lobbies at each Floor level overband Underground Water Tanks	70%
10	External plumbing and external Plaster, lubrication, completion of terraces with waterproofing of the building/ wing	70%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of area apartment to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A

The Golden Heritage Row House 99

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Self Floor	100%
6	Slabs of Super Structure:	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fixings Within the Flat/Premises	70%
9	Mainwater, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	70%
11	Installation of Lifts, Water pumps, Fire Fighting Fixings and Equipment as per CFO NOC, Electrical Fixings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A

The Golden Heritage Row House 98

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (If any)	100%
3	Podium (If any)	0%
4	Plinth	100%
5	1st Floor	0%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	70%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	70%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby / s, plinth Protection, Paving of areas appertenant to Building/ Wing, Compound wall and all other equipments as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A

The Golden Heritage Row House 89

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Exhausts (if any)	0%
4	Plinth	100%
5	Soft Floor	0%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/ Premises	70%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	70%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CHO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / URB/ NDC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A

The Golden Heritage Row House 100

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1.	Excavation	100%
2.	Retainments (if any)	100%
3.	Podiums (If any)	0%
4.	Pilecap	100%
5.	Self Floor	0%
6.	Slabs of Super Structure	100%
7.	Internal Walls, Internal Passes, Floorings, Doors and Windows Within Flats / Premises	100%
8.	Sanitary Fittings Within the Flat/Premises	70%
9.	Staircases, Lifts Wells and Lobby at each Floor level overhead Underground Water Tanks	70%
10.	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	70%
11.	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance in conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	70%

Table A

The Golden Heritage Row House 101

Sr. No.	Task/Activity	Percentage of actual work done (As on 31.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	0%
4	Plinth	100%
5	Soft Floor	0%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/ Premises	70%
9	Staircases, Lifts Wells and Lobbies at each Floor level, overhead Underground Water Tanks	70%
10	External plumbing and external Floor, Elevation, completion of terraces with waterproofing of the building/ wing	70%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipments as per CEO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / EIA/ NCM, Finishing to entrance Lobby/s, plinth Protection, Raising of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A
The Golden Heritage Row House 102

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Slit Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	60%
8	Sanitary Fittings Within the Flat/Premises	50%
9	Staircases, Lifts Wells and Lobbies at each floor level, overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	50%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPD NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth protection, Paving of areas appurtenant to building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	50%

Table A

The Golden Heritage Row House 103

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Full Floor	100%
6	Slab of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat / Premises	60%
8	Sanitary Fittings Within the Flat / Premises	50%
9	Staircases, Lifts Wells and Lobbies at each Floor level, overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of services with waterproofing of the building / wing	50%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby / A, finish Protection, Paving at areas appurtenant to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	50%

Table A
The Golden Heritage Row House 104

Sr. No	Task/Activity	Percentage of actual work done (As on 31.05.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Pediments (if any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, internal plaster, Plastering, Doors and Windows Within Floor / Terraces	60%
8	Sanitary Fittings Within the Flat/Terraces	50%
9	Staircases, Lifts Wells and Lobbies at each floor level overhead, Underground Water Tanks	50%
10	External plastering and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	50%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CMAA NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	50%

Table A

The Golden Heritage Row House 105

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	60%
8	Sanitary Fittings Within the Flat / Premises	30%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	30%
10	Internal plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building / wing.	50%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO/NOC, Electrical Fittings, Mechanical Equipments, Compliances to conditions of environment / CRZ-NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	50%

Table A

The Golden Heritage Row House 106

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.05.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podium (If any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	60%
8	Boundary Fillings Within the Flat/Premises	30%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building / wing	50%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/A, plinth Protection, Paving of areas appurtenant to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	50%

Table A

The Golden Heritage Row House 107

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	60%
8	Sanitary Fittings Within the Flat/Premises	50%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terrace with waterproofing of the building / wing	50%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CKZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	50%

Table A

The Golden Heritage Row House 108

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (If any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat / Premises	60%
8	Sanitary Fittings Within the Flat/Premises	50%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevator, Completion of terraces with waterproofing of the building/wing	50%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance lobby/s, plinth Erection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	50%

Table A
The Golden Heritage Row House 109

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Full Floor	100%
6	Slab of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	60%
8	Sanitary Fittings Within the Flat / Premises	50%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building / wing.	50%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per GFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	50%

Table A

The Golden Heritage Row House 110

Sr. No	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (If any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Full Floor	100%
6	Slabs of Super Structure	30%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	30%
8	Sanitary Fittings Within the Flat / Premises	30%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	30%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building / wing.	30%
11	Installation of Lifts /Water pumps, Fire Fighting Fittings and Equipment as per CPD NOC, Electrical Fittings, Mechanical Equipments, Compliance in conditions of environment / CRZ NOC, Finishing to entrance Lobby /s, Plinth Protection, Drivng of areas appurtenant to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	30%

Table A
The Golden Heritage Row House III

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Fill Floor	100%
6	Slabs of Super Structure	50%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat / Premises	70%
8	Sanitary Fittings Within the Flat / Premises	30%
9	Staircase, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building / wing	80%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per ETO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/a, plinth Protection, Paving of main approach to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of ssa. Any other activities.	30%

Table A

The Golden Heritage Row House 112

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2014)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Slit Floor	100%
6	Slabs of Super Structure	50%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	30%
8	Sanitary Fixings Within the Flat/Premises	30%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	80%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	50%
11	Installation of Lifts, Water pumps, Fire Fighting Fixings and Equipments as per C/O NOC, Electrical Fixings, Mechanical Equipments, Compliance in conditions of environment / CRZ NOC, Finishing to entrance Lobby /s, Plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale, Any other activities.	30%

Table A

The Golden Heritage Bow House 113

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Soil Floor	100%
6	Slabs of Super Structure	50%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	50%
8	Sanitary Fittings Within the Flat/Premises	50%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead & Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building / wing.	50%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPD NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NCC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	50%

Table A

The Colium Heritage Row House 114

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2023)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Foofoms (if any)	100%
4	Plinth	100%
5	5th Floor	100%
6	Slabs of Super Structure	50%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	30%
8	Sanitary Fittings Within the Flat/Premises	30%
9	Smrtaes, Lifts Wells and Lockers at each floor level overhead Underground Water Tanks	30%
10	External plastering and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	30%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NCC, Electrical Fixings, Mechanical Equipments, Compliance to consultants of environment / CRZ NCC, Finishing to entrance Lobby/s, Plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale, Any other activities.	30%

Table A

The Golden Heritage Row House 115

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Silt Floor	100%
6	Slabs of Super Structure	50%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Plots / Premises	40%
8	Sanitary Fixings Within the Plot/Premises	30%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead / Underground Water Tanks	30%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building / wing.	30%
11	Installation of Lifts /Water pumps, Fire Fighting Fittings and Equipment as per CPC-NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / ERZ-NOC, Finishing in entrance Lobby /A, ground Provision, Paving of areas appertenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	30%

Table A

The Golden Heritage Rose House 116

Sr. No	Task/Activity	Percentage of actual work done (As on 30.06.2023)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Sub Floor	100%
6	Slabs of Super Structure	30%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	30%
8	Sanitary Fittings Within the Flat/Premises	30%
9	Staircases, Lift Wells and Lobbies at each Floor level overhead Underground Water Tanks	30%
10	External plumbing and external Plaster, Elevators, completion of terraces with waterproofing of the building/ wing.	30%
11	Installation of Lifts, Waste pumps, Fire Fighting Fittings and Equipment as per CDD/NOC, Electrical Fittings, Mechanical Equipments / Compliance to conditions of environment / CRZ/NOC, Finishing to entrance Lobby / a. plinth Protection, Paving of areas appertenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale, Any other activities	30%

Table A

The Golden Heritage Row House 117

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (If any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Slab Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	70%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead / Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CDD-NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of encroachment / CRZ-NOC, Finishing in entrance/ Lobby/s, plinth Protection, Paving of areas appertaining to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A

The Golden Heritage Row House 158

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Full floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat /Terraces	100%
8	Sanitary Fittings Within the Flat/Terraces	70%
9	Staircases, Lifts Wells and Lobbies at each floor level overhead / Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of services with waterproofing of the building/wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Plants and Equipment as per CPD NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NCC, Finishing to entrance Lobby/a, plinth Protection, Paving of areas appertenant to building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale, Any other activities.	70%

Table A

The Golden Heritage Row House-119

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(A)	(B)	(C)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Soil Floor	100%
6	Slab of Super Structure	100%
7	Internal Walls, Internal Plaster, Flooring, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	70%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead / Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building / wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipments as per CRZ NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby / a, plinth Protection, Paving of area appurtenant to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	70%

Table A

The Golden Heritage Row House 129

Ser. No.	Task/Activity	Percentage of actual work done (As on 31.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Pediments (if any)	100%
4	Plinth	100%
5	Grill Floor	100%
6	Bole of Super Structure	100%
7	Internal Walls, Internal Plaster, Fixings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	70%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby / a, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications to agreement of sale. Any other activities	70%

Table A

The Golden Heritage Row House 121

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Disassembly (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Sub Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flats/Premises	70%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance in conditions of environment / CR2 NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appertaining to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	70%

Table A
The Golden Heritage Row House 111

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (If any)	100%
3	Podiums (If any)	100%
4	Pierch	100%
5	Slit Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flats/Premises	70%
9	Staircases, Lifts, Walls and Lobbies at each Floor level overhead Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting fittings and Equipments as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of encasement / CIG NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appertenant to building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A

The Golden Heritage Row House 125

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Pediments (if any)	0%
4	Plinth	0%
5	Slit Floor	0%
6	Slab of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Escalators, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevations, completion of terraces with waterproofing of the building/ wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO, NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ, NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to building/ Wing, Completion well and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A
The Golden Heritage Row House 129

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (if any)	0%
4	Plinth	0%
5	Sub Floor	0%
6	Slab of Super Structure	0%
7	Internal Walls, Internal Plaster, Flooring, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	0%
11	Installation of Lifts /Water pumps, Fire Fighting Fittings and Equipment as per CPC NOC , Electrical Fittings, Mechanical Equipments, Compliance in conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas adjacent to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	0%

Table A
The Golden Heritage Row House 127

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1.	Excavation	100%
2.	Basements (if any)	0%
3.	Pedestals (if any)	0%
4.	Plinth	0%
5.	Sub Floor	0%
6.	Subs of Super Structure	0%
7.	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8.	Sanitary Fixings Within the Flat/Premises	0%
9.	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10.	External plumbing and external plaster, elevation, completion of terraces with waterproofing of the building/wing	0%
11.	Installation of Lifts, Water pumps, Fire Fighting Fixings and Equipment as per EPC MCC, Electrical Fixings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance lobby / s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	0%

Table A
The Golden Heritage Row House 128

Sl. No.	Task/Activity	Percentage of actual work done (As on 31.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Pediments (if any)	0%
4	Plinth	0%
5	Soil Floor	1%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flat / Premises	0%
9	Sanitarys, Lifts, Wells and Lobbies at each floor level overhead / Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CDD, NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ, NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas adjacent to Building/Wing, Compounded wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities:	0%

Table A

The Golden Heritage II, House 128

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (If any)	0%
3	Podiums (If any)	0%
4	Plinth	0%
5	Slab Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level, covered Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPDND, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ, VCC, Finishing to entrance Lobby/a, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A
The Golden Heritage Row House 130

S/o. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (if any)	0%
4	Plinth	0%
5	Soil Bore	0%
6	Sole of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External planking and external Plaster, Elevation, completion of façades with waterproofing of the building/wing.	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFD NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CR2 NOC, Finishing to entrance Lobby/s, plant Protection, Paving of access apparatus to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A
The Golden Heritage Row House 131

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (if any)	0%
4	Plinth	0%
5	Slab Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flat/ Premises	0%
9	Strengthen Lifting Wells and Ladders at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plating, Erection, completion of terraces with waterproofing of the building/ wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of access apartment in building/ wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	0%

Table A
The Golden Heritage Row House 132

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (if any)	0%
4	Plinth	0%
5	Soil Floor	0%
6	Slab of Super Structure	10%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level, overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance in conditions of environment / CRZ NOC, Finishing in entrance Lobby / i.e. plinth Protection, Paving of area appurtenant to building/ Wing, Compounded wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other schemes.	0%

Table A
The Golden Heritage Row House 135

<i>Sl. No.</i>	<i>Task/Activity</i>	<i>Percentage of actual work done (As on 30.06.2024)</i>
(i)	(ii)	(iii)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (if any)	0%
4	Plinth	0%
5	Slab Floor	3%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Roofings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of services with waterproofing of the building/wing.	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/D NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby / s, plants Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A
The Golden Heritage Row House 134

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (if any)	0%
4	Plinth	0%
5	5th Floor	0%
6	State of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flat / Premises	0%
9	Staircases, Lifts, Walls and Lobbies at each Floor level overhead / Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevations, completion of terraces with waterproofing of the building / wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO / DC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ / NOC, Finishing to entrance Lobby / s, Plinth Protection, Paving of areas appurtenant to Building / Wing, Compoured wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	0%

Table A
The Golden Heritage New House 135

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (if any)	0%
4	Plinth	0%
5	Self Floor	0%
6	Slab of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Plots / Premises	0%
8	Sanitary Fittings Within the Plot / Premises	0%
9	Staircases, Lifts Wells and Lobby at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building / wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CIO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby / s, plinth Protection, Paving of areas appurtenant to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A
The Golden Heritage Home House 136

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basement (if any)	0%
3	Podiums (if any)	0%
4	Plinth	0%
5	Silt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat / Premises	0%
8	Sanitary Fixings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of facades with waterproofing of the building/wing.	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fixings and Equipment as per CDD NOC, Electrical Fixings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House 137

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (if any)	0%
4	Plinth	0%
5	Slit Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flat / Premises	0%
9	Staircases, Lifts Walls and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPC NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby /s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A
The Golden Heritage Row House 134

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (if any)	0%
4	Plinth	0%
5	Still Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows within Plaza / Premises	0%
8	Sanitary Fittings Within the Flat / Premises	0%
9	Staircases, Lift Wells and Lobbies at each floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Finishing, completion of terraces with waterproofing of the building/ wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/O NCC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A
The Golden Heritage Row House 189

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Foundation (If any)	0%
3	Podiums (If any)	0%
4	Plinth	0%
5	Mill Floor	0%
6	Roof of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each floor level overhead & Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per C/D NCC, Electrical Fittings, Mechanical Equipments, Compliance in conditions of environment / CRZ, NOC, Paving to entrance Lobby/s, plant Protection, Paving of access appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	0%

Table A

The Golden Heritage Row House 140

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1.	Excavation	100%
2.	Basements (if any)	0%
3.	Podiums (if any)	0%
4.	Plinth	0%
5.	Slit Floor	0%
6.	Slabs of Super Structure	0%
7.	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8.	Sanitary Fittings Within the Flat/Premises	0%
9.	Staircases, Lifts Wells and Lobbies at each floor level overhead Underground Water Tanks	0%
10.	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	0%
11.	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFC NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CSE/ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	0%

Table A.

The Golden Heritage Row Houses 143

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (If any)	0%
3	Podiums (If any)	0%
4	Plinth	0%
5	Slab Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevators, completion of terraces with waterproofing of the building/ wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per G.O. NOC. Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appertaining to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	0%

Table A

The Golden Heritage Row House 142

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (If any)	0%
3	Pediments (If any)	0%
4	Plinth	0%
5	Soil Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flats / Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building / wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance in conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building / Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale, Any other activities	0%

Table A

The Golden Heritage Row House 143

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2025)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (if any)	0%
4	Plinth	0%
5	Self Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fixings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fixings and Equipment as per C/O NCC, Electrical Fixings, Mechanical Equipments, Compliance to conditions of environment / CRZ NCC, Finishing to entrance Lobby /s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities	0%

Table A

The Golden Heritage Row House 144

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Volumes (if any)	0%
4	Plinth	0%
5	Slab Floor	0%
6	State of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flat / Premises	0%
8	Sanitary Fittings Within the Flat/ Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	0%
11	Installation of Lifts, Water pumps, Fire Fighting, Fittings and Equipments as per G.O/NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CKZ NOC, Flashing to entrance Lobby/a. plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Res House 145

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.06.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Raasements (if any)	0%
3	Podfams (if any)	0%
4	Plinth	0%
5	Self Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level, overhead Underground Water Tanks	0%
10	External painting and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per ETC NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing treatment Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table B

Common Areas (Internal & External Development Works) in respect of the registered phase /project number

Sr.No.	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Actual Work Done (As on 30.06.2024)	Details
(1)	(2)	(3)	(4)	(5)
1.	Internal Roads and Footpaths	Yes	0%	Paver Blocks
2.	Water Supply	Yes	33%	Water Connection Pipeline
3.	Sewerage (sanitary, Lines, Septic Tank, STP)	Yes	40%	Septic Tank With Soak Pit
4.	Storm Water Drains	No	0%	NA
5.	Landscaping & Tree Planting	Yes	0%	Only Tree Planting in Club House Area
6.	Street Lighting	Yes	30%	NA
7.	Community Buildings	No	0%	NA
8.	Treatment and Disposal of Sewage and Sullage water	No	0%	NA
9.	Solid Waste Management & Disposal	No	0%	NA
10.	Water Conservation/ Rain Water harvesting	Yes	0%	Only Rain Water Harvesting
11.	Energy Management	No	0%	NA
12.	Fire Protection And Fire Safety Requirements	No	0%	NA
13.	Electrical meter room, Sub-Station, Receiving station	No	0%	NA
14.	Open Parking	No	0%	NA
15.	Entrance Gate With Security Cabin	Yes	0%	NA
16.	Aggregate area of recreational Open Space	Yes	0%	Club House



Yours Faithfully

D.N. JOSHI ARCHITECTS
D.N. JOSHI ARCHITECTS
ARCHITECTS & INTERIORS
PLOT NO. 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000

MR. DHANANJAY KARENDRA JOSHI

(Case No. CA/2002/29133)

Agreed and Accepted by

For The Golden Heritage

M/S THE GOLDEN HERITAGE
PARTNERS
Partner Mr. Anand

Date: 08.08.2024