



D.N. Joshi Architects, Nandurbar

Dhananjay Narendra Joshi CA/2002/29199, AIA 26721, AIN 7337
Architects, Interior Designers

Office 01 Address:
C/15, Fourth Floor, Suvarna Park,
Opp. Maratha Mandir, Bavdhan
PUNE Dist- Pune-411021(M.S.)
M.no-09112643585
Mail id- ar_djoshi78@yahoo.co.in
GST NO- 27AGUPJ2463J2ZV

Office 02 Address :
Plot no-17, Lokmanya colony,
Nandurbar Dist-Nandurbar - 425412
M.no- 9403868585

Pan No - AGUPJ2463J
TAN NO - N5KD08649E

Form 1

(See Regulation 3)

ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing project and for
Withdrawal of Money from Designated Account)

Date: 05.11.2024

To,
The Partners,
The Golden Heritage
S No. 94/2/B, Near Vijay Shree Nagar,
Hole Shiwar, Nandurbar,
Tal. & Dist. Nandurbar-425412.

Subject: Certificate of percentage of completion of construction work of "**The Golden Heritage**" having MahaRERA Registration Number: P49700029921 being developed by The Golden Heritage.

Sir,

I, Mr. Dhananjay Narendra Joshi have undertaken assignment as Architect/Licensed Surveyor of certifying percentage of Completion of Construction work of the "**The Golden Heritage**" having MahaRERA Registration Number: P49700029921 being developed by The Golden Heritage.

Based on site inspection, with respect to layout/each of the building/wing of the aforesaid Real Estate project, I certify that as on the date of this certificate, the percentage of work done for each of the building/wing of the Real Estate project under MahaRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in table B.

M/S THE GOLDEN HERITAGE

PARTNERS




Table A
The Golden Heritage Row House 3

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%

THE GOLDEN HERITAGE

PARTNERS



D.N. JOSHI ARCHITECTS

ARCHITECTS & INTERIORS
PLOT 17, LOKMANYA COLONY
NANDURBAR-425412 M. 9112843555
email-ar_djoshi76@yahoo.co.in

5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls,+Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts,Water pumps,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipment,Compliance to conditions of environment / CRZ NOC,Finishing to entrance Lobby/s,plinthProtection,Paving of areas appurtenant to Building/Wing,Compound wall and all other requirements as may berequired tocomplete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 4

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%

10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 5

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 6

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 7

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 8

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/ Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing,	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby /s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 9

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 10

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby /s, plinth Protection, Paving of areas appertenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 11

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/ Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 12

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 13

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/ Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CTO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 14

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 15

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead, Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 16

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 17

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 18

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead : Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 19

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 20

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Silt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 21

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 22

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	0%
4	Plinth	0%
5	Stilt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	0%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House 23

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 24

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CPO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby /s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 25

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/ Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 26

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 27

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/ Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 28

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Grill Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 29

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CEZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 30

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 31

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 32

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing,	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A
The Golden Heritage Row House 33

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing,	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A
The Golden Heritage Row House 34

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Silt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A

The Golden Heritage Row House 35

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CPO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A
The Golden Heritage Row House 36

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A

The Golden Heritage Row House 51

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A

The Golden Heritage Row House 52

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A

The Golden Heritage Row House 53

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A
The Golden Heritage Row House 54

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A

The Golden Heritage Row House 55

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 56

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A

The Golden Heritage Row House S7

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A
The Golden Heritage Row House 58

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 59

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 60

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 61

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 62

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Silt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 63

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 64

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 65

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	80%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A

The Golden Heritage Row House 66

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	80%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A

The Golden Heritage Row House 67

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	80%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A
The Golden Heritage Row House 68

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	80%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A
The Golden Heritage Row House 69

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 70

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 71

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 72

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	80%
8	Sanitary Fittings Within the Flat/Premises	50%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	60%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A
The Golden Heritage Row House 73

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	80%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A

The Golden Heritage Row House 74

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	80%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	60%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing,	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CPO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A

The Golden Heritage Row House 75

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	80%
8	Sanitary Fittings Within the Flat/Premises	75%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead : Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A

The Golden Heritage Row House 76

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	80%
8	Sanitary Fittings Within the Flat / Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A

The Golden Heritage Row House 77

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	80%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CPO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A
The Golden Heritage Row House 78

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CPO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 79

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	80%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A

The Golden Heritage Row House 80

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 81

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A
The Golden Heritage Row House 82

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Silt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	80%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	80%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A

The Golden Heritage Row House 83

Sl. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	80%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	80%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A
The Golden Heritage Row House 84

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	80%
8	Sanitary Fittings Within the Flat/Premises	80%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead , Underground Water Tanks	80%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	80%

Table A

The Golden Heritage Row House 85

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	80%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	80%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A

The Golden Heritage Row House 86

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	80%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	80%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A

The Golden Heritage Row House 87

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	80%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	80%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing,	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A

The Golden Heritage Row House 88

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	80%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead / Underground Water Tanks	80%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing,	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/ s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A
The Golden Heritage Row House 89

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	100%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	100%

Table A

The Golden Heritage Row House 90

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat / Premises	75%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead. Underground Water Tanks	75%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	75%

Table A

The Golden Heritage Row House 91

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	75%
8	Sanitary Fittings Within the Flat/Premises	75%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	75%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	75%

Table A
The Golden Heritage Row House 92

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	75%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	75%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	75%

Table A

The Golden Heritage Row House 93

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	75%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	75%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	75%

Table A

The Golden Heritage Row House 96

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	100%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing,	70%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A
The Golden Heritage Row House 97

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	70%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	70%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A

The Golden Heritage Row House 98

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	0%
4	Plinth	100%
5	Stilt Floor	0%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	70%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	70%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A

The Golden Heritage Row House 99

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	0%
4	Plinth	100%
5	Stilt Floor	0%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	70%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	70%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A

The Golden Heritage Row House 100

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	0%
4	Plinth	100%
5	Stilt Floor	0%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	70%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	70%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A

The Golden Heritage Row House 101

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	0%
4	Plinth	100%
5	Stilt Floor	0%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	70%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	70%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A

The Golden Heritage Row House 102

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	80%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	60%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	60%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	50%

Table A

The Golden Heritage Row House 103

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	80%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	60%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	60%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CPO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	50%

Table A
The Golden Heritage Row House 104

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	80%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	60%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	60%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	50%

Table A

The Golden Heritage Row House 105

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	80%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	60%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	60%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	60%

Table A

The Golden Heritage Row House 106

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	80%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	60%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	60%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	50%

Table A

The Golden Heritage Row House 107

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	80%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	60%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	60%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	50%

Table A

The Golden Heritage Row House 108

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	80%
8	Sanitary Fittings Within the Flat/Premises	60%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	60%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	60%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	50%

Table A

The Golden Heritage Row House 109

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	50%
8	Sanitary Fittings Within the Flat/Premises	50%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	50%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	50%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CPO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	50%

Table A
The Golden Heritage Row House 110

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	50%
8	Sanitary Fittings Within the Flat/Premises	30%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead & Underground Water Tanks	30%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	30%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	30%

Table A

The Golden Heritage Row House 111

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Silt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	50%
8	Sanitary Fittings Within the Flat/Premises	30%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	30%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	30%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	30%

Table A

The Golden Heritage Row House 112

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	50%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	50%
8	Sanitary Fittings Within the Flat/Premises	30%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	30%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing,	30%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	30%

Table A

The Golden Heritage Row House 113

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	50%
8	Sanitary Fittings Within the Flat/Premises	30%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	30%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	30%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	30%

Table A

The Golden Heritage Row House 114

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2023)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	50%
8	Sanitary Fittings Within the Flat/Premises	30%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	30%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	30%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	30%

Table A

The Golden Heritage Row House 115

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	50%
8	Sanitary Fittings Within the Flat/Premises	30%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	30%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	30%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	30%

Table A

The Golden Heritage Row House 116

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	50%
8	Sanitary Fittings Within the Flat/Premises	30%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	30%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	30%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	30%

Table A

The Golden Heritage Row House 117

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	70%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A

The Golden Heritage Row House 118

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	100%
8	Sanitary Fittings Within the Flat/Premises	70%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A

The Golden Heritage Row House 119

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (if any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	70%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A
The Golden Heritage Row House 120

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	70%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CPO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A

The Golden Heritage Row House 121

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	100%
8	Sanitary Fittings Within the Flat/Premises	70%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A

The Golden Heritage Row House 122

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	100%
3	Podiums (If any)	100%
4	Plinth	100%
5	Stilt Floor	100%
6	Slabs of Super Structure	100%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	70%
8	Sanitary Fittings Within the Flat/Premises	70%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	70%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing,	100%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	70%

Table A

The Golden Heritage Row House 125

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (If any)	0%
4	Plinth	0%
5	Stilt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing,	0%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House 126

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (if any)	0%
4	Plinth	0%
5	Stilt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	0%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House 127

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (If any)	0%
4	Plinth	0%
5	Stilt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	0%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC. Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House 128

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (If any)	0%
4	Plinth	0%
5	Stilt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flat / Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	0%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House 129

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (If any)	0%
4	Plinth	0%
5	Stilt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A
The Golden Heritage Row House 130

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (If any)	0%
4	Plinth	0%
5	Stilt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls ,internal Plaster, Floorings, Doors and Windows Within Flats /Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	0%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House 131

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (If any)	0%
4	Plinth	0%
5	Stilt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	0%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A
The Golden Heritage Row House 132

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (if any)	0%
4	Plinth	0%
5	Stilt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	0%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby /s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House 133

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (If any)	0%
4	Plinth	0%
5	Stilt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	0%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House 134

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (if any)	0%
4	Plinth	0%
5	Silt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	0%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House 135

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (if any)	0%
4	Plinth	0%
5	Stilt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	0%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House 136

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (if any)	0%
4	Plinth	0%
5	Soil Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	0%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House 137

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (If any)	0%
4	Plinth	0%
5	Stilt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	0%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House 138

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (If any)	0%
4	Plinth	0%
5	Stilt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	0%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/ Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House 139

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (If any)	0%
4	Plinth	0%
5	Stilt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House 140

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (If any)	0%
4	Plinth	0%
5	Stilt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	0%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House 141

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (If any)	0%
4	Plinth	0%
5	Stilt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	0%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House 142

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (If any)	0%
4	Plinth	0%
5	Stilt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing.	0%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House 143

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (if any)	0%
4	Plinth	0%
5	Stilt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls, Internal Plaster, Floorings, Doors and Windows Within Flats / Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing,	0%
11	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House 144

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (If any)	0%
4	Plinth	0%
5	Stilt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead , Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/ wing,	0%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table A

The Golden Heritage Row House 145

Sr. No.	Task/Activity	Percentage of actual work done (As on 30.09.2024)
(1)	(2)	(3)
1	Excavation	100%
2	Basements (if any)	0%
3	Podiums (If any)	0%
4	Plinth	0%
5	Silt Floor	0%
6	Slabs of Super Structure	0%
7	Internal Walls ,Internal Plaster, Floorings, Doors and Windows Within Flats /Premises	0%
8	Sanitary Fittings Within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level overhead . Underground Water Tanks	0%
10	External plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building/wing.	0%
11	Installation of Lifts ,Water pumps ,Fire Fighting Fittings and Equipment as per CFO NOC , Electrical Fittings, Mechanical Equipments ,Compliance to conditions of environment / CRZ NOC. Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to complete the project as per specifications in agreement of sale. Any other activities.	0%

Table B

Common Areas (Internal & External Development Works) in respect of the registered phase /project number

sr.No.	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Actual Work Done (As on 30.09.2024)	Details
(1)	(2)	(3)	(4)	(5)
1.	Internal Roads and Footpaths	Yes	30%	Paver Blocks
2.	Water Supply	Yes	30%	Water Connection Pipeline
3.	Sewerage (chamber, Lines, Septic Tank, SIP)	Yes	30%	Septic Tank With Soak Pit
4.	Storm Water Drains	No	0%	NA
5.	Landscaping & Tree Planting	Yes	0%	Only Tree Planting in Club House Area
6.	Street Lighting	Yes	30%	NA
7.	Community Buildings	No	0%	NA
8.	Treatment and Disposal of Sewage and Sullage water	No	0%	NA
9.	Solid Waste Management & Disposal	No	0%	NA
10.	Water Conservation/Rain Water harvesting	Yes	0%	Only Rain Water Harvesting
11.	Energy Management	No	0%	NA
12.	Fire Protection And Fire Safety Requirements	No	0%	NA
13.	Electrical meter room, Sub-Station, Receiving station	No	0%	NA
14.	Open Parking	No	0%	NA
15.	Entrance Gate With Security Cabin	Yes	0%	NA
16.	Aggregate area of recreational Open Space	Yes	0%	Club House

Yours Faithfully



MR. DHANANJAY NARENDRA JOSHI

(License No. CA/2002/29199)

D.N.JOSHI ARCHITECTS
ARCHITECTS & INTERIORS
P.NO. 17 LOKMANYA COLONY
HANDLUNBAR-425412 M.-9112543585
arnold-ar_joshi78@yahoo.co.in

Agreed and Accepted by:

For, The Golden Heritages

M/S THE GOLDEN HERITAGE

PARTNERS

Name: Mr. Anand Hastimal Jain

Date: 05.11.2024