



SYED MOBIN ARCHITECTS

301, P 7/2, Style Homes, Chitnavis Layout,
Byramji Town, Nagpur- 13 (MS) India.
+91-0712-2588900 & 901
sma.info.ngp@gmail.com
syedmobin.com

Annexure A

FORM 1

[see Regulation 3]

ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)

Date: 07/07/25

To,
OAK STERLING VISTA LLP
NAGPUR, MAHARASHTRA, 440001

Subject : Certificate of percentage of Work of completion of construction work of **OAK STERLING VISTA** having MahaRERA Registration Number **P50500055834** (Only Applicable after project Registration) being developed by **OAK STERLING VISTA LLP**

Sir,
I/We **SYED MOBIN ARCHITECTS** have undertaken assignment as Architect /Licensed Surveyor of certifying Percentage of completion of Construction Work of **OAK STERLING VISTA** having MahaRERA Registration Number **P50500055834** (Only Applicable after project Registration, being developed by **OAK STERLING VISTA LLP**)

Based on Site Inspection, with respect to Layout / each of the Building/Wing of the aforesaid Real Estate Project I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project under MahaRERA is as per Table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

Table A

Layout/Building/Wing Number: WING A/NA

Sr. No.	Tasks/Activity	Percentage of Actual Work Done (As on date of the Certificate)
(1)	(2)	(3)
1	Excavation	100.00
2	Basements (if any)	80.00
3	Podiums (if any)	0.00
4	Plinth,	95.00
5	Stilt Floor	80.00
6	Slabs of Super Structure	95.00
7	Internal walls, Internal plaster, Floorings, Floors and windows within Flats/Premises	30.00
8	Sanitary Fitting within the Flat/Premises	0.00



Sr. No.	Tasks/Activity	Percentage of Actual Work Done (As on date of the Certificate)
9	Staircases, lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	60.00
10	External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0.00
11	Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Any other activities.	0.00

Layout/Building/Wing Number: WING B/NA

Sr. No.	Tasks/Activity	Percentage of Actual Work Done (As on date of the Certificate)
(1)	(2)	(3)
1	Excavation	100.00
2	Basements (if any)	80.00
3	Podiums (if any)	0.00
4	Plinth,	95.00
5	Stilt Floor	80.00
6	Slabs of Super Structure	0.00
7	Internal walls, Internal plaster, Floorings, Floors and windows within Flats/Premises	0.00
8	Sanitary Fitting within the Flat/Premises	0.00
9	Staircases, lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	0.00
10	External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0.00
11	Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Any other activities.	0.00

Layout/Building/Wing Number: WING C/NA

Sr. No.	Tasks/Activity	Percentage of Actual Work Done (As on date of the Certificate)
(1)	(2)	(3)
1	Excavation	0.00
2	Basements (if any)	0.00
3	Podiums (if any)	0.00
4	Plinth,	0.00
5	Stilt Floor	0.00
6	Slabs of Super Structure	0.00
7	Internal walls, Internal plaster, Floorings, Floors and windows within Flats/Premises	0.00
8	Sanitary Fitting within the Flat/Premises	0.00
9	Staircases, lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	0.00
10	External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0.00
11	Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Any other activities.	0.00



Phase / Project Number)

Sr.No	Common areas and facilities	Proposed (Yes / No)	Percentage of Actual Work Done (As on date of the Certificate)	Details
(1)	(2)	(3)	(4)	(5)
1	Internal Roads & Footpaths	No	0.00	NA
2	Water Supply	Yes	0.00	BOREWELL/ CORPORATIO N WATER SHALL BE PROVIDED
3	Sewerage (Chamber, Lines, Septic Tank , STP)	Yes	0.00	AS PER SANCTIONED PLAN
4	Storm Water Drains	Yes	0.00	AS PER SANCTIONED PLAN
5	Landscaping & Tree Planting	Yes	0.00	AS PER SANCTIONED PLAN
6	Street Lighting	No	0.00	NA
7	Community Buildings	No	0.00	NA
8	Treatment And Disposal Of Sewage And Sullage Water	No	0.00	NA
9	Solid Waste Management And Disposal	No	0.00	NA
10	Water conservation /Rain water harvesting	Yes	0.00	AS PER SANCTIONED PLAN
11	Energy managemcnt	No	0.00	NA
12	Fire protection and fire safety requirements	Yes	0.00	AS PER SANCTIONED PLAN
13	Electrical meter room, sub-station, receiving station	Yes	0.00	AS PER SANCTIONED PLAN
14	Aggregate area of recreational Open Space	No	0.00	NA
15	Open Parking	No	0.00	NA

Yours Faithfully

SYED MOBIN ARCHITECTS

Signature & Name (IN BLOCK LETTERS) of L.S/ Architect
(License No: CA/2002/29182)



Date of Certificate: 07/07/25

Agreed and accepted by:

Signature of Promoter

Name: OAK STERLING VISTA LLP

Date: 07/07/2025