

Architect, Planner, Landscape Architect, Interior Designer, Cover, Valuer

Vistaar Heights, 4th floor, Plot No.146-151, Opp. Shree Gajanan Maharaj Mandir,

Zenda Chowk, Dharampeth, NAGPUR-10.

M.NO. 9422103220

FORM-2A

[See Regulation 3A.]

ENGINEERS'S CERTIFICATE FOR QUALITY ASSURANCE

(Site Supervisor's Certificate)

(To be submitted at the end of Financial Year)

Date:

To,

The SHIV REALITIES

Nagpur (M Corp.), Nagpur (Urban), Nagpur, 440027

Quality Assurance Certificate

(Certificate No. for the Year Ending 31/03/2026.....)

Subject : Certificate for quality of materials used and quality of Construction and workmanship of the work of **SHIV****GANGA PARK B-WING** having MahaRERA Registration Number **P50500079003** being developed by _____
SHIV**REALITIES**

Sir,

I C.D.Giripunje have undertaken an assignment of supervision of this real estate project

Our Responsibility

To carry out the work in accordance with the development permission and as per the approved plan, to submit certificate of supervision of work, to carry out material testing in-situ or in an authorized laboratory as per prevailing and applicable standards, to ensure quality of work and workmanship as per prescribed specifications, and as per

NBC and / or other relevant code of practice.

The details of the quality are as follows :

1. Structural Design, Stability and Testing**2. Input Materials**

Sr. No.	Parameters	Yes/No	Remarks
1	Whether the following building materials confirm to relevant IS/BS/NBC Code, or as per Industry Standards? If yes, provide details:	No	

	(a) Cement, concrete and coarse aggregate	No	
	(b) Steel and its alloys	No	
	(c) Electrical wire, fittings and accessories	No	
	(d) Plumbing and sanitary fittings	No	
2	Whether regular tests of materials and construction products are being done from accredited labs also? If yes, details of such labs	No	
3	Whether manufacturer test certificate for cement, steel, pipes etc. have been obtained and whether supply records are being maintained?	No	
4	Whether suitable water is being used for construction?	No	
	(i) What is the source of water?	No	
	(ii) Has water been tested and approved by Engineer-in-Charge before construction?	No	
	(iii) Has water been tested subsequently as per requirement?	No	


3. Quality of Workmanship

Sr. No.	Parameters	Yes/No	Remarks
1	Whether works of all the electrical wiring/connections/lift installation/other electrical installations have been carried out under authorized/registered electrical engineer and whether records of the same has been maintained?	No	
2	Whether all related works of plumbing & sanitary including installation of water supply systems, drainage systems, sewage systems, sinks, toilets etc. have been carried out under authorized/registered plumbers/sanitary contractors and whether records of the same has been maintained?	No	
3	Whether all the work is being carried out under supervision of experienced and skilled professional? Further, whether the workmanship and quality is satisfactory and up to the mark and the work is within the acceptable and permissible limits of deviations as per relevant Code of Practice?	No	
Sr. No.	Parameters	Yes/No	Remarks
4	Whether remedial measures are undertaken to prevent dampness and leakages? If yes, provide details	No	
5	Whether safety precautions are undertaken during construction activities for all type of workers?	No	

4. Miscellaneous

Sr. No.	Parameters	Yes/No	No
1	Whether third party quality inspection is being carried out on site during/after completion of the works? If yes, provide details.	No	
2	Whether anti-termite treatment has been undertaken for the soil?	No	
3	Whether fire-fighting arrangements has been undertaken under supervision of fire consultant?	No	
4	Whether proper signages have been installed on site/completed building as per requirement?	No	
5	Whether precautions are undertaken to avoid air pollution during construction? Please specify.	No	
6	Whether records of all test reports/results have been properly kept in the prescribed formats and whether the same are available at site for viewing by allottees and to be handed over to the association of allottees?	No	
7	Whether all relevant records including sanctioned building plans, utility drawings, various test reports/results have been properly kept in the prescribed formats to be handed over to the association of allottees?	No	
8	Any innovative/cost effective/green technology has been used for improving quality/energy efficiency? Please specify.	No	

Yours Faithfully

SHIV REALITIES

PARTNER PARTNER

Agreed and accepted by

Signature of Promoter

Name: SHIV

REALITIES Date:

Signature of Engineer (Site Supervisor)

Name: C D GIRIPUNJE

Qualification (Not less than graduate) License No. (if any):

Phone No:

Place:


ARCHITECT
C.D. Giripunj
C.A./2001/278
M.I.T. No.132
M.M.C. No.R-1