

FORM 1 [see Regulation 3]
ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account-
Building/Wing wise)

Date: 01/04/2021

To

Bhuvi Landmarks LLP,
Plot No. 29/45, Bhaishree Chambers, Opp. ADCC Stadium, Kamgar Chowk,
N-2, CIDCO,
Aurangabad.

Subject: Certificate of Percentage of Completion of Construction Work of **Row house nos. 1 to 11 Building(s)/ ___ Wing(s) of MadhuBan [MAHA RERA REGISTRATION NO. P51500020977]** situated on the **Gut No 37, Plot No - 21, Village - Hirapur TQ & DIST- Aurangabad PIN 431001**, demarcated by its boundaries (latitude and longitude of the end points) **19° 86' 92.28" North and 75° 43' 90.07" East**, to the

North – 12 mtr wide road,
South – Land of Gut No 36,
East – Land of Gut No 41,
West – Open Space and 9 mtr wide road,

Taluka & dist. **Aurangabad** PIN 431203, admeasuring **1085.15** Sq.mt. area, being developed by **Bhuvi landmarks LLP**.

Sir,

We **Samil Architects** have undertaken assignment as Architect /Licensed Surveyor of certifying Percentage of Completion of Construction Work of the **Row house nos. 1 to 11 Building of the Project MadhuBan [MAHA RERA REGISTRATION NO. P51500020977]** situated on the **Gut No 37, Plot No - 21, Village - Hirapur TQ & DIST- Aurangabad PIN 431001** admeasuring **1085.15** Sq.mt. area being developed by **Bhuvi landmarks LLP**.

1. Following technical professionals are appointed by Owner / Promoter: -
- M/s/ SAMIL ARCHITECTS (Ar. Sameer Ausekar) (Reg. No CA – 95/19301), Aurangabad** as an Architect;
 - M/s S.R. CONSULTANTS (Er. Ravindra Y. Bansode), Aurangabad** as Structural Consultant.

Nishigandh – C, Disha Srushti, Opp. Hotel Atithi, Rana Nagar, Jalna Road, Aurangabad.- 431005
Call - +91 240 2451616 E – Mail – info@samilarchitects.com Web Site – www.samilarchitects.com

III. M/s/ **SAMIL INTERIORS (Er. Milind Wadekar) (Reg. No 152/92)**, Aurangabad as Consulting an Engineer.

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number **P51500020977** is as per table A herein below. The percentage of the work executed with respect to each of the major activity of the **Row house nos. 1 to 61 Building** and Overall Percentage of work done with respect to each Building is detailed in the Table B.

Table A

(To be prepared separately for each Building/Wing of the Project)

ROW HOUSES 1 TO 4

Sr. No	Tasks /Activity	Percentage of work done
1	Excavation	100 %
2	1 Number of Plinth	100 %
3	0 Number of Basement Floor	0 %
4	0 Number of Silt Floor	0 %
5	1 Number of Slabs of Super Structure	100 %
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100 %
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	100 %
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100 %
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100 %
10	Installation of lifts, water pumps, Fire-Fighting Fittings and Equipment as per GFO-NOC, Electrical fittings to Common Areas, electro-mechanical equipment, Compliance to conditions of environment /CRZ-NOC, finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate Occupation /Completion Certificate	50 %

ROW HOUSE 5

Sr. No	Tasks /Activity	Percentage of work done
1	Excavation	100 %
2	1 Number of Plinth	100 %
3	0 Number of Basement Floor	0 %
4	0 Number of Stilt Floor	0 %
5	2 Number of Slabs of Super Structure	100 %
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100 %
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	100 %
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100 %
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	100 %
10	Installation of lifts, water pumps, Fire-Fighting-Fittings and Equipment as per CFC-NOC, Electrical fittings to Common Areas, electro-mechanical equipment, Compliance to conditions of environment /CRZ-NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate Occupation /Completion Certificate	100 %

ROW HOUSE 6

Sr. No	Tasks /Activity	Percentage of work done
1	Excavation	100 %
2	1 Number of Plinth	100 %
3	0 Number of Basement Floor	0 %
4	0 Number of Stilt Floor	0 %
5	2 Number of Slabs of Super Structure	100 %

6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100 %
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	100 %
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100 %
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	100 %
10	Installation of lifts, water pumps, Fire-Fighting-Fittings-and-Equipment-as-per-CFO-NOC, Electrical fittings to Common Areas, electro-mechanical equipment, Compliance to conditions of environment /CRZ-NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	100 %

ROW HOUSES 7 TO 11

Sr. No	Tasks /Activity	Percentage of work done
1	Excavation	100 %
2	1 Number of Plinth	100 %
3	0 Number of Basement Floor	0 %
4	0 Number of Stilt Floor	0 %
5	1 Number of Slabs of Super Structure	100 %
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100 %
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	100 %
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100 %
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	100 %
10	Installation of lifts, water pumps, Fire Fighting-Fittings-and-	50 %

Equipment as per CFO-NOC, Electrical fittings to Common Areas, electro-mechanical equipment, Compliance to conditions of environment /CRZ-NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate Occupation /Completion Certificate	
--	--

TABLE-B

Internal & External Development Works in Respect of the entire Registered Phase

Sr. No.	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details
1.	Internal Roads & Footpaths	Yes	100%	Only Paved surface in Tremix Concrete No Foot Paths
2.	Water Supply	Yes	100%	Through Bore well and JMC water supply when available.
3.	Sewerage (chamber, lines, Septic Tank, STP)	Yes	100%	Chambers, Drainage lines Septic Tank. No STP
4.	Storm Water Drains	No		
5.	Landscaping & Tree Planting	Yes	100%	Work not started yet
6.	Aggregate Area Of Recreational open Space	No	0%	Fencing, Gate etc. as per Norms
7.	Street Lighting	Yes	50%	As per Norms
8.	Community Buildings	No		-----
9.	Treatment and disposal of sewage and sullage water	Yes		Work yet to be started
10.	Solid Waste management & Disposal	No		-----

11.	Water conservation, Rain water harvesting	Yes	75%	Rain Water harvesting As per mandatory conditions
12.	Energy management	No		---
13.	Fire protection and fire safety requirements	No		---
14.	Electrical meter room, sub-station, receiving station	Yes	75%	As per drawings of Consultants
15.	Others Compound Wall & Entrance Gate	Yes	100%	

Overall Project completion is 94.68% for building A4 and 82.84% for Internal & External development works.

Yours Faithfully



Sign
Er. Milind M. Wadekar
Regd. No : E - 152 / 92

For,
SAMIL ARCHITECTS

SAMIL ARCHITECTS
Nishigandh - C, Disha Srushti,
Rana Nagar, Opp Hotel Atithi,
Jaina Road, Aurangabad - 431005
Ph - 0240-2451616.
email-samil@live.in