

FORM 1
[see Regulation 31]
ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)

To.

DATE: 31/12/2025

Laxmibai Shankar Ghatge
At Post, Banewadi, Near Maroti Mandir
Railway Station Road, Aurangabad(MH)-431001.

Subject: Certificate of Percentage of Completion of Construction Work of Project: **SHUBHARAMBH** having MahaRERA Registration Number **P51500020577** being developed by **Laxmibai Shankar Ghatge**.

Sir,

I/ We **Er Vaibhav V Budhwant** have undertaken assignment as Architect /Licensed Surveyor of certifying Percentage of Completion of project **SHUBHARAMBH** for Construction Work having MahaRERA Registration Number **P51500020577** being developed by **Laxmibai Shankar Ghatge**.

Based on Site inspection with respect to Layout / each of the of theafore said Real-estate Project. I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project under MahaRERA is as per Table A herein below. Percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B

TABLE-A

(To be prepared separately for each Layout building/Wing of The Project)
Block A Wing 3 BHK Row House (101-108)

Sr No (1)	Tasks / Activity (2)	Percentage of Actual Work Done (As on date of this Certificate) (3)
1.	Excavation	100%
2.	Basement's (if any)	N.A.
3.	Podiums (if any)	N.A.
4.	Plinth	100%
5.	Stilt Floor	100%
6.	Slabs of Super Structure	100%
7.	Internal walls, Internal Plaster, Floorings, I) doors and	100%

Shop No. 2, plot No. 326, Infront of CIDCO office,
Mahanagar-I, Tisgoan, Waluj, CIDCO,
Ch. Sambhajinagar-431136.
dhassociate810@gmail.com

	windows within Flats/Premises	
8	Sanitary Fittings within the Flat/Premises	100%
9	Staircases. lifts' Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	100%
10	External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/wing.	100%
11	Installation of Lifts. water pumps, Fire Fitting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, compliance to conditions of environment/CRZ NOC. Finishing to entrance lobby/s. plinth protection, paving of areas appurtenant to Building/Wing. Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Any other activities.	N.A.

Block B Wing 3 BHK Row House (201-208)

Sr No (1)	Tasks / Activity (2)	Percentage of Actual Work Done (As on date of this Certificate) (3)
1.	Excavation	100%
2.	Basement's (if any)	N.A.
3.	Podiums (if any)	N.A.
4.	Plinth	100%
5.	Stilt Floor	100%
6.	Slabs of Super Structure	100%
7.	Internal walls, Internal Plaster, Floorings, l) doors and windows within Flats/Premises	100%
8	Sanitary Fittings within the Flat/Premises	100%
9	Staircases. lifts' Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	100%
10	External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/wing.	100%


11	Installation of Lifts. water pumps, Fire Fitting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, compliance to conditions of environment/CRZ NOC. Finishing to entrance lobby/s. plinth protection, paving of areas appurtenant to Building/Wing. Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Any other activities.	N.A.
----	---	------

Block C Wing 3 BHK Row House (301-304)

Sr No (1)	Tasks / Activity (2)	Percentage of Actual Work Done (As on date of this Certificate) (3)
1.	Excavation	100%
2.	Basement's (if any)	N.A.
3.	Podiums (if any)	N.A.
4.	Plinth	100%
5.	Stilt Floor	100%
6.	Slabs of Super Structure	100%
7.	Internal walls, Internal Plaster, Floorings, I) doors and windows within Flats/Premises	100%
8	Sanitary Fittings within the Flat/Premises	100%
9	Staircases. lifts' Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	100%
10	External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/wing.	100%
11	Installation of Lifts. water pumps, Fire Fitting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, compliance to conditions of environment/CRZ NOC. Finishing to entrance lobby/s. plinth protection, paving of areas appurtenant to Building/Wing. Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Any other activities.	N.A.

Block D Wing 3 BHK Row House (401-404)

📍 Shop No. 2, plot No. 326, Infront of CIDCO office,
 📧 Mahanagar-I, Tisgoan, Waluj, CIDCO,
 Ch. Sambhajinagar-431136.
 dhassociate810@gmail.com



Sr No (1)	Tasks / Activity (2)	Percentage of Actual Work Done (As on date of this Certificate) (3)
1.	Excavation	100%
2.	Basement's (if any)	N.A.
3.	Podiums (if any)	N.A.
4.	Plinth	100%
5.	Stilt Floor	0%
6.	Slabs of Super Structure	50%
7.	Internal walls, Internal Plaster, Floorings, I) doors and windows within Flats/Premises	10%
8.	Sanitary Fittings within the Flat/Premises	0%
9.	Staircases. lifts' Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	0%
10.	External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/wing.	0%
11.	Installation of Lifts. water pumps, Fire Fitting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, compliance to conditions of environment/CRZ NOC. Finishing to entrance lobby/s. plinth protection, paving of areas appurtenant to Building/Wing. Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Any other activities.	N.A.

Block E Wing 3 BHK Row House (501-504)

Sr No (1)	Tasks / Activity (2)	Percentage of Actual Work Done (As on date of this Certificate) (3)
1.	Excavation	100%
2.	Basement's (if any)	N.A.
3.	Podiums (if any)	N.A.
4.	Plinth	100%
5.	Stilt Floor	100%
6.	Slabs of Super Structure	100%
7.	Internal walls, Internal Plaster, Floorings, I) doors and windows within Flats/Premises	60%

📍 Shop No. 2, plot No. 326, Infront of CIDCO office,
 📧 Mahanagar-I, Tisgoan, Waluj, CIDCO,
 Ch. Sambhajinagar-431136.
 dhassociate810@gmail.com

8	Sanitary Fittings within the Flat/Premises	0%
9	Staircases. lifts' Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	15%
10	External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/wing.	0%
11	Installation of Lifts. water pumps, Fire Fitting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, compliance to conditions of environment/CRZ NOC. Finishing to entrance lobby/s. plinth protection, paving of areas appurtenant to Building/Wing. Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Any other activities.	N.A.

TABLE-B
Common Areas (Internal and External Development Works) in respect of the Registered Phase/Project Number

Sr No (1)	Common areas and facilities (2)	Proposed (Yes/No) (3)	Percentage of Actual Work Done (As on date of the Certificate) (4)	Details (5)
1.	Internal Roads & Footpaths	Yes	WBM Done	Only paves surface No Footpaths
2.	Water Supply	Yes	0%	Through Bore well & authority water supply when available
3.	Sewerage (Chamber, lines, Septic Tank, STP).	Yes	70%	Chambers, Drainage line Septic tank
4.	Storm Water Drains	No		

5.	Landscaping & Tree Planting	Yes	0%	Only Tree plantation in open space
6.	Street Lighting	Yes	15%	
7.	Community Buildings			
8.	Treatment and disposal of sewage and sullage water.	No	0%	Septic tank
9.	Solid Waste management & Disposal	No	0%	
10.	Water conservation / Rain water harvesting	Yes		
11.	Energy management.	No		
12.	fire protection and fire Safety requirements	No		
13.	Electrical meter room, sub-station, receiving station.	Yes	100%	Separate DP
14.	Compound Wall	Yes	50%	

Your's Faithfully,

Er Vaibhav V Budhwant

(License No. DDMCB/R/2024/APL/01781)


Er. Vaibhav V. Budhwant
REG. NO. DDMCB/R/2024/APL/01781
Consulting Civil Engineer

Agreed and Accepted by:

Laxmibai Shantabai Chate

LAXMI

Date: **Proprietor**

(Proprietor)

Place: Aurangabad

📍 Shop No. 2, plot No. 326, Infront of CIDCO office,
Mahanagar-I, Tisgoan, Waluj, CIDCO,
Ch. Sambhajinagar-431136.
dhassociate810@gmail.com

