



rahul thole and associates

architects. interior designers

1st floor, laxmi sankul, near sant eknath rang mandir, usmanpura, aurangabad 423001
info@rahultholearchitects.com mobile : 9422202459

Annexure A

FORM 1

[See Regulation 3]

ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing Project & for Withdrawal of Money from Designated Account)

Date: 13-10-2025

To,
**MAHAVIR INFRASTRUCTURE – PROP. RUPESH PRAKASHCHAND MUTHA,
FIRST FLOOR, PLOT NO 7,RH NO 82, BLUE BELLS, NEAR PROZONE MALL,
MIDC CHIKALTHANA, CHHATRAPATI SAMBHAJI NAGAR**

Subject: Certificate of Percentage of Completion of Construction Work of **55 HAPPYNES**T having MahaRERA Registration Number **P51500052128** being developed by **MAHAVIR INFRASTRUCTURE – PROP. RUPESH PRAKASHCHAND MUTHA**.

Sir,

I / We **RAHUL THOLE & ASSOCIATES** have undertaken assignment as Architect / Licensed Surveyor of Certifying Percentage of Completion of Construction Work of **55 HAPPYNES**T having MahaRERA Registration Number **P51500052128** being developed by **MAHAVIR INFRASTRUCTURE – PROP. RUPESH PRAKASHCHAND MUTHA**.

Based on the Site Inspection, with respect to the Layout / each Building/Wing of the aforesaid Real Estate Project, I certify that as on date of this Certificate, the Percentage of Work Done for each of the Building/Wing of the Real Estate Project under MahaRERA is as per Table-A herein below. The percentage of work executed with respect to each of the activity of entire Phase is detailed in Table-B.

TABLE-A

Layout / Building / Wing Number **of 55 HAPPYNES**T **BUILDING A**

S. No.	Tasks / Activity	Percentage of Actual Work Done (As on date of the Certificate)
(1)	(2)	(3)
1.	Excavation	0%
2.	Basements (if any)	0%
3.	Podiums (if any)	0%
4.	Plinth	0%
5.	Stilt Floor	0%
6.	Slab of Super Structure	0%
7.	Internal Walls, Internal Plaster, Floorings, Doors, windows within Flats / Premises	0%
8.	Sanitary Fittings within Flats / Premises	0%
9.	Staircases, Lift Wells & Lobbies at each Floor Level Overhead and Underground Water Tanks	0%
10.	External Plumbing & External Plaster, Elevation, Completion of Terraces, with waterproofing of the Building / Wing	0%
11.	Installation of Lifts, Water Pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of Environment / CRZ NOC, Finishing to Entrance Lobby/s, Plinth Protection, Paving of Areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete Project as	0%

	per specifications to Agreement of Sale, Any other Activity	
--	---	--

TABLE-A
Layout / Building / Wing Number of 55 HAPPYNES BUILDING B

S. No.	Tasks / Activity	Percentage of Actual Work Done (As on date of the Certificate)
(1)	(2)	(3)
1.	Excavation	0%
2.	Basements (if any)	0%
3.	Podiums (if any)	0%
4.	Plinth	0%
5.	Stilt Floor	0%
6.	Slab of Super Structure	0%
7.	Internal Walls, Internal Plaster, Floorings, Doors, windows within Flats / Premises	0%
8.	Sanitary Fittings within Flats / Premises	0%
9.	Staircases, Lift Wells & Lobbies at each Floor Level Overhead and Underground Water Tanks	0%
10.	External Plumbing & External Plaster, Elevation, Completion of Terraces, with waterproofing of the Building / Wing	0%
11.	Installation of Lifts, Water Pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of Environment / CRZ NOC, Finishing to Entrance Lobby/s, Plinth Protection, Paving of Areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete Project as per specifications to Agreement of Sale, Any other Activity	0%

TABLE-A
Layout / Building / Wing Number of 55 HAPPYNES BUILDING C

S. No.	Tasks / Activity	Percentage of Actual Work Done (As on date of the Certificate)
(1)	(2)	(3)
1.	Excavation	100%
2.	Basements (if any)	-----
3.	Podiums (if any)	-----
4.	Plinth	100%
5.	Stilt Floor	100%
6.	Slab of Super Structure	100%
7.	Internal Walls, Internal Plaster, Floorings, Doors, windows within Flats / Premises	100%
8.	Sanitary Fittings within Flats / Premises	95%
9.	Staircases, Lift Wells & Lobbies at each Floor Level Overhead and Underground Water Tanks	100%
10.	External Plumbing & External Plaster, Elevation, Completion of Terraces, with waterproofing of the Building / Wing	100%
11.	Installation of Lifts, Water Pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of Environment / CRZ NOC, Finishing to Entrance Lobby/s, Plinth Protection, Paving of Areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete Project as per specifications to Agreement of Sale, Any other Activity	95%

TABLE-A
Layout / Building / Wing Number of 55 HAPPYNES BUILDING D

S. No.	Tasks / Activity	Percentage of Actual Work Done (As on date of the Certificate)
(1)	(2)	(3)
1.	Excavation	100%
2.	Basements (if any)	-----
3.	Podiums (if any)	-----

4.	Plinth	100%
5.	Stilt Floor	100%
6.	Slab of Super Structure	100%
7.	Internal Walls, Internal Plaster, Floorings, Doors, windows within Flats / Premises	100%
8.	Sanitary Fittings within Flats / Premises	95%
9.	Staircases, Lift Wells & Lobbies at each Floor Level Overhead and Underground Water Tanks	100%
10.	External Plumbing & External Plaster, Elevation, Completion of Terraces, with waterproofing of the Building / Wing	100%
11.	Installation of Lifts, Water Pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of Environment / CRZ NOC, Finishing to Entrance Lobby/s, Plinth Protection, Paving of Areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete Project as per specifications to Agreement of Sale, Any other Activity	95%

TABLE-A
Layout / Building / Wing Number ___ of 55 HAPPYNESST BUILDING E

S. No.	Tasks / Activity	Percentage of Actual Work Done (As on date of the Certificate)
(1)	(2)	(3)
1.	Excavation	100%
2.	Basements (if any)	-----
3.	Podiums (if any)	-----
4.	Plinth	100%
5.	Stilt Floor	100%
6.	Slab of Super Structure	100%
7.	Internal Walls, Internal Plaster, Floorings, Doors, windows within Flats / Premises	70%
8.	Sanitary Fittings within Flats / Premises	60%
9.	Staircases, Lift Wells & Lobbies at each Floor Level Overhead and Underground Water Tanks	100%
10.	External Plumbing & External Plaster, Elevation, Completion of Terraces, with waterproofing of the Building / Wing	50%
11.	Installation of Lifts, Water Pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of Environment / CRZ NOC, Finishing to Entrance Lobby/s, Plinth Protection, Paving of Areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete Project as per specifications to Agreement of Sale, Any other Activity	60%

TABLE-A
Layout / Building / Wing Number ___ of 55 HAPPYNESST BUILDING F

S. No.	Tasks / Activity	Percentage of Actual Work Done (As on date of the Certificate)
(1)	(2)	(3)
1.	Excavation	100%
2.	Basements (if any)	-----
3.	Podiums (if any)	-----
4.	Plinth	80%
5.	Stilt Floor	0%
6.	Slab of Super Structure	0%
7.	Internal Walls, Internal Plaster, Floorings, Doors, windows within Flats / Premises	0%
8.	Sanitary Fittings within Flats / Premises	0%
9.	Staircases, Lift Wells & Lobbies at each Floor Level Overhead and Underground Water Tanks	0%
10.	External Plumbing & External Plaster, Elevation, Completion of Terraces, with waterproofing of the Building / Wing	0%
11.	Installation of Lifts, Water Pumps, Fire Fighting Fittings and	0%

	Equipments as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of Environment / CRZ NOC, Finishing to Entrance Lobby/s, Plinth Protection, Paving of Areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete Project as per specifications to Agreement of Sale, Any other Activity	
--	--	--

TABLE-A
Layout / Building / Wing Number of 55 HAPPYNES **BUILDING G**


S. No.	Tasks / Activity	Percentage of Actual Work Done (As on date of the Certificate)
(1)	(2)	(3)
1.	Excavation	100%
2.	Basements (if any)	-----
3.	Podiums (if any)	-----
4.	Plinth	100%
5.	Stilt Floor	100%
6.	Slab of Super Structure	100%
7.	Internal Walls, Internal Plaster, Floorings, Doors, windows within Flats / Premises	100%
8.	Sanitary Fittings within Flats / Premises	95%
9.	Staircases, Lift Wells & Lobbies at each Floor Level Overhead and Underground Water Tanks	100%
10.	External Plumbing & External Plaster, Elevation, Completion of Terraces, with waterproofing of the Building / Wing	95%
11.	Installation of Lifts, Water Pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical Fittings, Mechanical Equipments, Compliance to conditions of Environment / CRZ NOC, Finishing to Entrance Lobby/s, Plinth Protection, Paving of Areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete Project as per specifications to Agreement of Sale, Any other Activity	100%

TABLE-B
Common Areas (Internal & External Development Works) of 55 HAPPYNES **BUILDING A to G**

S. No.	Common Areas & Facilities	Proposed (Yes / NO)	Percentage of actual Work Done (As on date of Certificate)	Details
(1)	(2)	(3)	(4)	(5)
1.	Internal Roads & Footpaths	YES	10%	INTERNAL PROJECT TAR / CEMENT ROADS
2.	Water Supply	YES	30%	FROM BORE-WELL
3.	Sewerage (Chamber, Lines, Septic Tank, STP)	YES	10%	DRAINAGE LINE TILL CORPORATION LINE
4.	Strom Water Drains	NO	-----	N.A.
5.	Landscaping & Tree Planting	YES	60%	INTERNAL PROJECT TREE PLANTATION
6.	Street Lighting	YES	10%	INTERNAL PROJECT STREET LIGHTS
7.	Community Buildings	NO	-----	N.A.
8.	Treatment & Disposal of Sewage and Sullage Water	NO	-----	N.A.
9.	Solid Waste Management & Disposal	NO	-----	N.A.
10.	Water Conservation / Rain Water Harvesting	YES	10%	RAIN WATER HARVESTING AS PER NORMS
11.	Energy Management	NO	-----	N.A.
12.	Fire Protection & Fire Safety requirements	NO	-----	N.A.
13.	Electrical Meter Room, Sub-Station, Receiving Station	YES	0%	AS PER MSEB NORMS

Note: The certificate is been issued based on the data and progress report submitted by the site incharge and confirmed by the developers from time to time and for any deviation in the same, we shall not be accounted for it. This certificate is only to indicate the work progress and has nothing to do with any sort of commercial and monetary issues.

Yours faithfully,



ARCH. RAHUL THOLE

License Number : **CA / 97 / 21257**

Agreed & Accepted by:

MAHAVIR INFRASTRUCTURE

A handwritten signature in black ink, appearing to read "Rupesh Mutha".

Signature of Promoter

PROPRIETOR

Name: **MAHAVIR INFRASTRUCTURE – PROP. RUPESH PRAKASHCHAND MUTHA**

Date: **13-10-2025**