



AR. SOMNATH SHEVALE
B.Arch

9850043455
somonathshevale@gmail.com

4, SUNFLOWER, SUYOJIT GARDEN, GANGAPUR RD, NASHIK

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number _____ under MahaRERA is as per **Table A** herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

Table A

Building /Wing Number 16 (to be prepared separately for each Building /Wing of the Project)

Sr.No	Tasks /Activity	Percentage of work done
1	Excavation	100 %
2	16 number of Plinth	100 %
3	_____ Number of Podiums	N / A
4	Stilt Floor	N / A
5	32 Number of Slabs 2 NOS EACH UNIT of Super Structure	28 UNIT NO 1 TO 14 COMPLETED
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	80 %
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	50 %
8	Staircases, Lifts Wells and Lobbies at each floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	50 %
9	The external plumbing and external plaster, elevation, completion of terraces with	50 %