

**FORM 1 [see Regulation 3]
ARCHITECT'S CERTIFICATE**

Date : 4th January 2018

To
Sandeep Dwellers Pvt Ltd
3C, Gulmohar, Temple Road
Civil Lines, Nagpur – 440001

Subject: Certificate of Percentage of Completion of Construction Work of SPDL Aashray for Construction of 7 wings of the First Phase (MahaRERA Registration Number – P50500014329) situated on the Plot bearing Survey no. 260, Kh. No. 18/3, demarcated by its boundaries (21°10'05"N 78°59'45"E) to the North Kh No 18/2, to the South Kh No. 17 & 34, to the East Kh No. 20, to the West Kh No. 29 of Division Nagpur, Village Nagpur (M Corp.), Taluka Nagpur (Urban) District Nagpur PIN 440023, admeasuring 6944.50 Sq.mts. area being developed by Sandeep Dwellers Pvt. Ltd.

Sir,

I Rahul Agarwala have undertaken assignment as Architect /Licensed Surveyor of certifying Percentage of Completion of Construction Work of the 7 wings of the First Phase of the Project, situated on the plot bearing Survey no. 260, Kh. No. 18/3, demarcated by its boundaries (21°10'05"N 78°59'45"E) to the North Kh No 18/2, to the South Kh No. 17 & 34, to the East Kh No. 20, to the West Kh No. 29 of Division Nagpur, Village Nagpur (M Corp.), Taluka Nagpur (Urban) District Nagpur PIN 440023, admeasuring 6944.50 Sq.mts. area being developed by Sandeep Dwellers Pvt. Ltd.

1. Following technical professionals are appointed by Owner / Promoter:-

- (i) Shri Rahul Agarwala as L.S. / Architect
- (ii) Shri Prasanna Kulkarni as Structural Consultant
- (iii) Shri Rahul Agarwala as MEP Consultant
- (iv) Shri Prasanna Kulkarni as Quantity Surveyor *

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number – P50500014329 under MahaRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

Table A

Wing A & MHADA

Sr. No.	Tasks /Activity	Work Done %
		A
1	Excavation	100%
2	___ 1 ___ number of Plinth	100%
3	___ 0 ___ number of Podiums	0%
4	1 Stilt Floor	0%
5	___ 5 ___ number of Slabs of Super Structure	0%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0%
Total Work Done for the Wing / Building		9%

Wing B

Sr. No.	Tasks /Activity	Work Done %
		A
1	Excavation	100%
2	___ 1 ___ number of Plinth	100%
3	___ 0 ___ number of Podiums	0%
4	1 Stilt Floor	65%
5	___ 5 ___ number of Slabs of Super Structure	25%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%

8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0%
Total Work Done for the Wing / Building		22%

Wing C

Sr. No.	Tasks /Activity	Work Done %
		A
1	Excavation	100%
2	___ 1 ___ number of Plinth	100%
3	___ 0 ___ number of Podiums	0%
4	1 Stilt Floor	50%
5	___ 5 ___ number of Slabs of Super Structure	0%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0%
Total Work Done for the Wing / Building		13%

Wing D

Sr. No.	Tasks /Activity	Work Done %
		A
1	Excavation	100%
2	___ 1 ___ number of Plinth	100%
3	___ 0 ___ number of Podiums	0%
4	1 Stilt Floor	35%
5	___ 5 ___ number of Slabs of Super Structure	50%

6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0%
Total Work Done for the Wing / Building		28%

Wing E

Sr. No.	Tasks /Activity	Work Done %
		A
1	Excavation	100%
2	___1___ number of Plinth	50%
3	___0___ number of Podiums	0%
4	1 Stilt Floor	0%
5	___5___ number of Slabs of Super Structure	0%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0%
Total Work Done for the Wing / Building		6%

Wing F

Sr. No.	Tasks /Activity	Work Done %
		A
1	Excavation	100%
2	___1___ number of Plinth	25%

3	0 number of Podiums	
4	1 Stilt Floor	0%
5	5 number of Slabs of Super Structure	0%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0%
Total Work Done for the Wing / Building		5%

Wing M

Sr. No.	Tasks /Activity	Work Done %
		A
1	Excavation	100%
2	1 number of Plinth	100%
3	0 number of Podiums	0%
4	1 Stilt Floor	10%
5	5 number of Slabs of Super Structure	0%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0%
Total Work Done for the Wing / Building		9%

TABLE-B**Internal & External Development Works in Respect of the entire Registered Phase**

Sr. No.	Common areas and Facilities, Amenities	Work Done %	Details
		A	
1	Internal Roads & Footpaths	100%	
2	Water Supply	50%	NMC will supply water
3	Sewarage (chamber, lines, Septic Tank, STP)	25%	Chamber and lines will be connected to Existing NIT line.
4	Storm Water Drains	25%	Pipeline work will be done
5	Landscaping & Tree Planting	75%	Trees on periphery will be planted
6	Street Lighting	0%	
7	Community Buildings	90%	Club house will be made
8	Treatment and disposal of sewage and sullage water	0%	
9	Solid Waste management & Disposal	0%	Bins for solid waste collection will be put
10	Water conservation, Rain water harvesting	0%	2 nos. harvesting pits to be made
11	Energy management	50%	1% Solar power to be put
12	Fire protection and fire safety requirements	0%	As per law
13	Electrical meter room, sub-station, receiving station	0%	Transformer to be installed by MSEB
14	Generator Back up	0%	All common facilities on power back up
15	Security CCTV Camera	0%	For ground floor common areas
16	Lift	0%	Each wing has 1 lift
17	Society Office	0%	Not yet started
18	Aggregate area of recreational open space	90%	Compound wall work will be started
19	Open Parking	0%	Not yet started
	Total Work Done for the Wing / Building	41%	

Yours Faithfully



AR. RAHUL AGARWALA
REG NO. - CA/2008/41949
NMC - NMC / R - 529
NIT - LC. NO. 2310 COA

RAHUL AGARWALA

Architect

License No. _____