

**FORM 1 [see Regulation 3]  
ARCHITECT'S CERTIFICATE**

Date: 3<sup>rd</sup> October 21

To  
Sandeep Dwellers Pvt Ltd  
3C, Gulmohar, Temple Road  
Civil Lines, Nagpur – 440001

**Subject: Certificate of Percentage of Completion of Construction Work of  
SPDL Paradise II – C Wing  
MahaRERA Registration Number -P50500006021**

Sir,

I, Anand Sarda have undertaken assignment as Architect /Licensed Surveyor of certifying Percentage of Completion of Construction Work of the 1 Building of the Second Phase of the Project, situated on the plot bearing C.N. No/CTS No./ Survey No. 295 - Sheet No.72, Kh. No. 53/2, 54, 58, 59/3, demarcated by its boundaries (21°09'53"N 79°00'17"E) to the North – Road, to the South – City Survey No. 296, to the East – Road, to the West – City Survey No. 294 of Division Nagpur, Village Nagpur (M Corp.), Taluka Nagpur (Urban) District Nagpur PIN 440023, admeasuring 1153.82 Sq.mts. out of 8319.80 Sq.mts area being developed by Sandeep Dwellers Pvt. Ltd.

1. Following technical professionals are appointed by Owner / Promoter:-

- (i) Shri Anand Sarda as L.S. / Architect
- (ii) Shri Aman Kumar Singh as Structural Consultant
- (iii) Shri Anand Sarda as MEP Consultant
- (iv) Shri Aman Kumar Singh as Quantity Surveyor \*

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project , I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number - P50500006021 under MahaRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

**Table A**

Building /Wing Number C

| Sr.<br>No<br>. | Tasks /Activity                                                                                                               | Work<br>Done % |
|----------------|-------------------------------------------------------------------------------------------------------------------------------|----------------|
|                |                                                                                                                               | <b>A</b>       |
| 1              | Excavation                                                                                                                    | 100%           |
| 2              | <u>1</u> number of Plinth                                                                                                     | 100%           |
| 3              | <u>0</u> number of Podiums                                                                                                    | NA             |
| 4              | Stilt Floor                                                                                                                   | 100%           |
| 5              | <u>10</u> number of Slabs of Super Structure                                                                                  | 100%           |
| 6              | Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises             | 95%            |
| 7              | Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises                                      | 6%             |
| 8              | Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks | 100%           |
| 9              | The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,        | 65%            |

|    |                                                                                                                                                                                                                                                                                                                                                                                                                         |     |
|----|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|
| 10 | Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate | 0%  |
|    | <b>Total Work Done for the Wing / Building</b>                                                                                                                                                                                                                                                                                                                                                                          | 71% |

**TABLE-B**

**Internal & External Development Works in Respect of the entire Registered Phase**

| Sr. No | Common areas and Facilities, Amenities                | Work Done % |
|--------|-------------------------------------------------------|-------------|
|        |                                                       | <b>A</b>    |
| 1      | Internal Roads & Footpaths                            | NA          |
| 2      | Water Supply                                          | 100%        |
| 3      | Sewarage (chamber, lines, Septic Tank , STP)          | 100%        |
| 4      | Storm Water Drains                                    | 100%        |
| 5      | Landscaping & Tree Planting                           | 100%        |
| 6      | Street Lighting                                       | 0%          |
| 7      | Community Buildings                                   | 100%        |
| 8      | Treatment and disposal of sewage and sullage water    | 100%        |
| 9      | Solid Waste management & Disposal                     | 0%          |
| 10     | Water conservation, Rain water harvesting             | 90%         |
| 11     | Energy management                                     | 80%         |
| 12     | Fire protection and fire safety requirements          | 0%          |
| 13     | Electrical meter room, sub-station, receiving station | 0%          |
| 14     | Generator Back up                                     | 100%        |
| 15     | Security CCTV Camera                                  | 0%          |
| 16     | Lift                                                  | 0%          |
| 17     | Society Office                                        | 0%          |
| 18     | Aggregate area of recreational open space             | 100%        |
| 19     | Open Parking                                          | 0%          |
|        | <b>Total Work Done for the Wing / Building</b>        |             |

Yours Faithfully



**ANAND SARDA**  
Architect  
License No. COA – CA/99/24614  
NIT LS No. - 1196

**ANAND N. SARADA**  
Architect & Interior Designer  
COA Reg. No.: CA/99/24614  
NIT LS No.: 1196  
NIT LS No.: R-284