

**FORM 1 [see Regulation 3]
ARCHITECT'S CERTIFICATE**

Date : 3rd Oct 2020

To

Sandeep Dwellers Pvt Ltd
3C, Gulmohar, Temple Road
Civil Lines, Nagpur – 440001

Subject: Certificate of Percentage of Completion of Construction Work

Project: SDPL Royale

MahaRERA No: P50500016581

Sir,

I Rahul Agarwala have undertaken assignment as Architect /Licensed Surveyor of certifying Percentage of Completion of Construction Work of SDPL Royale for Construction of 1 building (MahaRERA Registration Number – P50500016581) situated on the Plot C bearing Survey no. 35, Kh. No. 25/1, demarcated by its boundaries (21°08'23"N 79°08'24"E) to the North Plot No Group B, to the South Kh No. 26, to the East Plot No 31,32,33, to the West 9 Mtr wide Road of Division Nagpur, Village Nagpur (M Corp.), Taluka Nagpur (Urban) District Nagpur PIN 440008, admeasuring 1416.46 Sq.mts. area being developed by Sandeep Dwellers Pvt. Ltd.

1. Following technical professionals are appointed by Owner / Promoter:-

- (i) Shri Rahul Agarwala as L.S. / Architect
- (ii) Shri Aman Kumar Singh as Structural Consultant
- (iii) Shri Rahul Agarwala as MEP Consultant
- (iv) Shri Aman Kumar Singh as Quantity Surveyor *

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number – P50500016581 under MahaRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

Sr. No.	Tasks /Activity	Work Done %
		A
1	Excavation	100%
2	_____1_____ number of Plinth	100%
3	_____0_____ number of Podiums	0%
4	1 Stilt Floor	100%
5	_____10_____ number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	70%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	16%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	50%

10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0%
Total Work Done for the Wing / Building		77%

TABLE-B

Internal & External Development Works in Respect of the entire Registered Phase

Sr. No.	Common areas and Facilities, Amenities	Work Done %
		A
1	Internal Roads & Footpaths	100%
2	Water Supply	80%
3	Sewerage (chamber, lines, Septic Tank , STP)	80%
4	Guard Room	0%
5	Aggregate area of recreational Open Space :	100%
6	Open Parking :	0%
7	Water Conservation, Rain water Harvesting :	0%
8	Energy management :	0%
9	Intercom :	0%
10	Fire Protection And Fire Safety Requirements :	0%
11	Storm Water Drains	80%
12	Landscaping & Tree Planting	50%
13	Street Lighting	100%
14	Lift	0%
15	Security CCTV camera	0%
16	Generator Back up	0%
Total Work Done for the Wing / Building		50%

Yours Faithfully



RAHUL AGARWALA

Architect

License No. _____

